



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Page 1 / 3

ESTIMATE

Date	: 23/06/2022	Reg No	: YQ5960K
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEA01BR2SDEP CBU MT
Attn.	:	Chassis No	: FEA01BA35337
Office / Mobile	:	Engine No	: 4P10E22602
Email Address	:	Quotation No.	: 158957
		Ref. No.	: GBE/SVC/SALES-HQ/207-2106
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 21/06/2022
Attn.	: CATHERINECHONGKL	Policy No.	: DHOM120064922200
Office / Mobile	:	Claim Type	: OD CLAIM - UNITED OVERSEAS INSURANCE
Email / Fax No.	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		GLASS,WINDSHIELD <i>cm</i>	1	1,012.50	-25	759.38	759.38
2		WEATHERSTRIP,WINDSHIELD <i>ne</i>	1	390.32	-25	292.74	292.74
3		GARNISH,FR PANEL <i>cut</i>	1	621.07	-25	465.80	465.80
4		GRILLE,RADIATOR <i>cm</i>	1	410.38	-25	307.78	307.78
5		PANEL, CAB FR CORNER -LH <i>cm</i>	1	549.75	-25	412.31	412.31
6		PANEL, CAB FR CORNER -RH <i>cm</i>	1	549.75	-25	412.31	412.31
7		CAP,MIRROR COVER RH <i>ms</i>	1	43.56	-25	32.67	32.67
8		PILLAR,FR RH <i>requis</i>	1	1,606.60	-25	1,204.95	1,204.95 <i>XR</i>
9		MARK,CANTER <i>ne</i>	1	115.06	-25	86.30	86.30
10		MARK,THREE-DIA <i>ne</i>	1	89.66	-25	67.25	67.25
11		PANEL ASSY,FRONT <i>bt</i>	1	2,832.78	-25	2,124.59	2,124.59
12		STAY,RR VIEW MIRROR -LH <i>bt</i>	1	497.88	-25	373.41	373.41
13		MIRROR,UNDER VIEW <i>cm</i>	1	60.35	-25	45.26	45.26
14		COVER,FR BMPR CORNER,LH <i>scr</i>	1	367.25	-25	275.44	275.44
15		COVER,FR BUMPER CORNER,RH <i>scr</i>	1	367.25	-25	275.44	275.44
16		GARNISH,HEADLAMP,LH <i>ms</i>	1	189.00	-25	141.75	141.75
17		GARNISH,HEADLAMP,RH <i>X</i>	1	189.00	-25	141.75	141.75 <i>X</i>
18		LAMP ASSY,TURN SIGNAL,FR LH <i>bro</i>	1	229.26	-25	171.95	171.95
19		LAMP ASSY,TURN SIGNAL,FR RH <i>bro</i>	1	229.26	-25	171.95	171.95
20		HEADLAMP ASSY,LH <i>cm</i>	1	696.91	-25	522.68	522.68
21		HEADLAMP ASSY,RH <i>cm</i>	1	696.91	-25	522.68	522.68
22		ARM W/SHLD WIPER <i>cm</i>	1	121.51	-25	91.13	91.13
23		BLADE ASSY,WIPER <i>ne</i>	1	52.77	-25	39.58	39.58
24		HEATER ASSY <i>?Xnn</i>	1	2,942.91	-25	2,207.18	2,207.18 <i>X</i>
25		DUCT,AIR CLEANER INTAKE <i>?Xnn</i>	1	790.78	-25	593.09	593.09 <i>X</i>

PARTS TOTAL : 7592.40 11,739.37


SPECIAL NETT ITEMS

1	IU BRACKET <i>ne</i>	1	15.00
2	COMPANY STICKER <i>ne</i>	1	150.00 <i>165</i>
PARTS TOTAL:			<u>215.00</u>

FUSO

AIRMAN

biSAFE
STAR





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Page 2 / 3

ESTIMATE

Date	: 23/06/2022	Reg No	: YQ5960K
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEA01BR2SDEP CBU MT
Attn.	:	Chassis No	: FEA01BA35337
Office / Mobile	:	Engine No	: 4P10E22602
Email Address	:	Quotation No.	: 158957
		Ref. No.	: GBE/SVC/SALES-HQ/207-2106
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 21/06/2022
Attn.	: CATHERINECHONGKL	Policy No.	: DHOM120064922200
Office / Mobile	:	Claim Type	: OD CLAIM - UNITED OVERSEAS INSURANCE
Email / Fax No.	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX FRONT WINDSCREEN	120	150.00
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	2700	4000.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	150	180.00
4	REFIX AIRCON SYSTEM AND TOP UP GAS. TO CHECK FUNCTION	X 600?	700.00
5	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1400	2000.00
6	TO REMOVE AND INSTALL MOBILEYE		350.00
7	TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD	X 600	700.00

LABOUR TOTAL : 8,080.00

SUB-TOTAL : 20,034.37

GST @ 7% for \$ 20,034.37 1,402.41

GRAND TOTAL (\$\$) : 21,436.78

LKK Auto Consultants will notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7592.40

165.00

4370.00

12,127.40

8 days

