

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY #07-16  
 AIG BUILDING, SINGAPORE 079120  
 TEL: 64193000 FAX: 68357416  
 ATTN: Motor Claim Department

**Estimate No:** EST2200194  
**Date:** 18 Jun 2022  
**Veh Reg No:** GBH8212L  
**Make/Model:** TOYOTA HIACE VAN  
 TURBO 4DR AT  
**Chasis No:** JTFHT02P000245263  
**Reg. Date:** 02/10/2018  
**Your Ref No:** SLL3373Z

**Claim Type:** Third Party  
**Accident Date:** 16/06/2022  
**TP Veh Reg No:** SLL3373Z

## Estimate Repair Cost to Vehicle No :GBH8212L

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
<b>List Price</b>			
1	1 PC BOOT LID	2,262.20	
2	1 PC BOOT LID LOGO	72.20	
3	1 PC BOOT LID RUBBER	368.90	
4	1 PC BOOT LID LOCK	349.60	
5	1 PC BOOT LID LOCK CHECKER	65.90	
6	1 PC BOOTLID TRIM	210.50	
7	1 PC BOOT LID "TOYOTA" STICKER	39.90	
8	1 PC BOOT LID "HIACE" EMBLEM	39.90	
9	1 PC REAR PANEL INNER	398.00	
10	1 PC REAR PANEL (OUTER)	481.30	
11	1 PC REAR PANEL TRIM	138.00	
12	1 PC REAR BUMPER	373.10	
13	2 PCS REAR BUMPER SIDE RETAINER	79.80	
		4,879.30	
	Less 25%	1,219.83	3,659.51
<b>Special Net</b>			
14	1 SET BOOT LID "ISO", 'SPIRIT OF ENTERPRISE','FACEBOOK', 'TRIPADVISOR' STICKER	380.00	
15	1 PC BOOT LID 'BONDING THROUGH THE POWER OF FUN' STICKER	250.00	
16	1 PC "70KM/H" STICKER	30.00	
17	1 SET BOOTLID TRIM CLIPS	40.00	
18	1 PC REAR WINDSCREEN SEAL	60.00	
19	1 PC REAR WINDSCREEN SEALANT	60.00	
20	1 SET REVERSE SENSORS	250.00	
21	1 SET REAR BUMPER CLIPS	40.00	
		1,110.00	1,110.00
<b>Labour</b>			
22	1 TO CHECK WIRING	50.00	

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

**Estimate No:** EST2200194  
**Date:** 18 Jun 2022  
**Veh Reg No:** GBH8212L  
**Make/Model:** TOYOTA HIACE VAN  
TURBO 4DR AT  
**Chasis No:** JTFHT02P000245263  
**Reg. Date:** 02/10/2018  
**Your Ref No:** SLL3373Z

**Claim Type:** Third Party  
**Accident Date:** 16/06/2022  
**TP Veh Reg No:** SLL3373Z

## Estimate Repair Cost to Vehicle No :GBH8212L

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
23	1	TO REPLACE STICKERS	100.00
24	1	TO REMOVE AND REFIT REAR WINDSCREEN	120.00
25	1	TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00
26	1	TO REMOVE AND REFIT REVERSE CAMERA	80.00
27	1	TO REMOVE AND REFIT REVERSE SENSOR	80.00
28	1	TO SPRAY PANEL SEALANT	120.00
29	1	(REAR) TO SPRAY PAINTING	1,000.00
30	1	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00
31	1	TO REMOVE AND REFIT INNER TRIM	150.00
		<u>2,780.00</u>	2,780.00
		Total	S\$ 7,549.51
		Add GST @ 7%	528.47
		Total Amount Payable	<u>S\$ 8,077.98</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SEVENTY SEVEN AND CENTS NINETY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE