

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY #07-16  
 AIG BUILDING, SINGAPORE 079120  
**TEL:** 64193000 **FAX:** 68357416  
**ATTN:** Motor Claim Department

**Estimate No:** EST2200194  
**Date:** 18 Jun 2022  
**Veh Reg No:** GBH8212L  
**Make/Model:** TOYOTA HIACE VAN  
 TURBO 4DR AT  
**Chasis No:** JTFHT02P000245263  
**Reg. Date:** 02/10/2018  
**Your Ref No:** SLL3373Z

**Claim Type:** Third Party  
**Accident Date:** 16/06/2022  
**TP Veh Reg No:** SLL3373Z

## Estimate Repair Cost to Vehicle No :GBH8212L

| Quantity           | Description   | List Price          | Amount    |
|--------------------|---|---------------------|-----------|
|                    |   | <u>SS</u>           | <u>SS</u> |
| <b>List Price</b>  |   |                     |           |
| 1                  | 1 PC BOOT LID <i>Dented</i>   | <del>2,262.20</del> | 2139      |
| 2                  | 1 PC BOOT LID LOGO <i>New</i>   | 72.20               | -         |
| 3                  | 1 PC BOOT LID RUBBER <i>2ut</i>   | 368.90              | -         |
| 4                  | 1 PC BOOT LID LOCK <i>Dented</i>  | 349.60              | -         |
| 5                  | 1 PC BOOT LID LOCK CHECKER <i>New</i>   | 65.90               | -         |
| 6                  | 1 PC BOOTLID TRIM <i>New</i>  | 210.50              | -         |
| 7                  | 1 PC BOOT LID "TOYOTA" STICKER <i>3 New</i>   | 39.90               | -         |
| 8                  | 1 PC BOOT LID "HIACE" EMBLEM  | 39.90               | -         |
| 9                  | 1 PC REAR PANEL INNER <i>Repair</i>   | 398.00              | -         |
| 10                 | 1 PC REAR PANEL (OUTER) <i>Dented</i>   | 481.30              | -         |
| 11                 | 1 PC REAR PANEL TRIM <i>Bent</i>  | 138.00              | -         |
| 12                 | 1 PC REAR BUMPER <i>Dented</i>  | 373.10              | -         |
| 13                 | 2 PCS REAR BUMPER SIDE RETAINER <i>New</i>  | 79.80               | -         |
|                    |   | 4,879.30            |           |
|                    | Less 25%  | 1,219.83            | 3,659.51  |
| <b>Special Net</b> |   |                     |           |
| 14                 | 1 SET BOOT LID "ISO", 'SPIRIT OF ENTERPRISE','FACEBOOK', 'TRIPADVISOR' STICKER <i>New</i> | <del>380.00</del>   | 280       |
| 15                 | 1 PC BOOT LID 'BONDING THROUGH THE POWER OF FUN' STICKER <i>New</i>                       | <del>250.00</del>   | 180       |
| 16                 | 1 PC "70KM/H" STICKER <i>New</i>  | 30.00               | 15        |
| 17                 | 1 SET BOOTLID TRIM CLIPS <i>New</i>   | 40.00               | -         |
| 18                 | 1 PC REAR WINDSCREEN SEAL <i>3 New</i>  | <del>60.00</del>    | 40        |
| 19                 | 1 PC REAR WINDSCREEN SEALANT <i>785</i>   | <del>60.00</del>    | 45        |
| 20                 | 1 SET REVERSE SENSORS <i>Dented</i>   | <del>250.00</del>   | 200       |
| 21                 | 1 SET REAR BUMPER CLIPS <i>New</i>  | <del>40.00</del>    | 30        |
|                    |   | 1,110.00            | 1,110.00  |
| <b>Labour</b>      |   |                     |           |
| 22                 | 1 TO CHECK WIRING   | 50.00               | 30        |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY #07-16  
 AIG BUILDING, SINGAPORE 079120  
**TEL:** 64193000 **FAX:** 68357416  
**ATTN:** Motor Claim Department

**Estimate No:** EST2200194  
**Date:** 18 Jun 2022  
**Veh Reg No:** GBH8212L  
**Make/Model:** TOYOTA HIACE VAN  
 TURBO 4DR AT  
**Chasis No:** JTFHT02P000245263  
**Reg. Date:** 02/10/2018  
**Your Ref No:** SLL3373Z

**Claim Type:** Third Party  
**Accident Date:** 16/06/2022  
**TP Veh Reg No:** SLL3373Z

## Estimate Repair Cost to Vehicle No :GBH8212L

| Quantity | Description   | List Price              | Amount             |
|----------|---|-------------------------|--------------------|
|          |   | <u>SS</u>               | <u>SS</u>          |
| 23       | 1 TO REPLACE STICKERS   | <del>100.00</del> 50    |                    |
| 24       | 1 TO REMOVE AND REFIT REAR WINDSCREEN   | 120.00 ✓                |                    |
| 25       | 1 TO REMOVE AND REFIT THIRD BRAKE LIGHT   | 80.00 +                 |                    |
| 26       | 1 TO REMOVE AND REFIT REVERSE CAMERA  | <del>80.00</del> 50     |                    |
| 27       | 1 TO REMOVE AND REFIT REVERSE SENSOR  | 80.00 50                |                    |
| 28       | 1 TO SPRAY PANEL SEALANT  | <del>120.00</del> 60    |                    |
| 29       | 1 (REAR) TO SPRAY PAINTING  | <del>1,000.00</del> 800 |                    |
| 30       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | <del>1,000.00</del> 800 |                    |
| 31       | 1 TO REMOVE AND REFIT INNER TRIM  | <del>150.00</del> 60    |                    |
|          |   | 2,780.00                | 2,780.00           |
|          |   | Total                   | SS 7,549.51        |
|          |   | Add GST @ 7%            | 528.47             |
|          |   | Total Amount Payable    | <u>SS 8,077.98</u> |

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SEVENTY SEVEN AND CENTS NINETY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

total: 5866.27 Adrian Lij  
 L/S: A7K H/S 23/06/22.  
 06 days  
 (A7K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: