

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0514/2022/JT
DATE : 22-Jun-22
WIP : 29668

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

5 days - ok - Johnny Boo

11-Dec-22

OWNER'S NAME : MR LAM JIA CONG, WILSON
ADDRESS : BLK 213 MARSILING CRESCENT
#12-61
SINGAPORE 730213
TELEPHONE : HP +65 98284283
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070162902
VEHICLE NO : **SLL 4664 C**
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 25/11/2020
ENGINE NO : DEM 026778
CHASSIS NO : WAUZZZF43MA012023
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-22
PLACE OF ACCIDENT : TAMPINES AVE 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 4664 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$	1,400.00		
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00		
5	TO DIMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	\$	1,500.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER.	\$	3,000.00	\$	1,650.00
6a	Add labour - see attached	\$	890.00	\$	890.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,412.00	\$	4,962.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	\$ 1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 393.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$ 174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	\$ 234.00
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 51.00	
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	1	\$ 293.00	\$ 234.00
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	\$ 120.40
9	FRONT BUMPER TRIM - RH	1	\$ 54.00	\$ 42.64
10	RADIATOR GRILLE	1	\$ 1,754.00	\$ 1,403.20
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 212.00	\$ 169.20
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
13	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$ 32.24
14	FRONT BUMPER TOP COVER	1	\$ 143.00	
15	CAUTION STICKER	1	\$ 16.00	
16	AIR COND STICKER	1	\$ 9.00	
17	FRONT BUMPER BRACKET LOCK CARRIER	1	\$ 154.00	\$ 122.80
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
19	FRONT BUMPER POP RIVET	4	\$ 4.00	
20	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 530.00	
SUB TOTAL SPARE PARTS		:	\$ 7,736.00	\$ 4,434.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	4,434.88
21	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
22	FRONT BUMPER WIRING SET	1	\$ 642.00		
23	HORN - RH	1	\$ 139.00		
24	HORN SUPPORT- RH	1	\$ 33.00		
25	FRONT FENDER - RH	1	\$ 1,227.00	\$	981.60
26	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 211.00		
27	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	\$	64.24
28	FRONT FENDER BRACKET - RH	1	\$ 41.00	\$	32.72
29	FRONT FENDER POP RIVET	7	\$ 27.00	\$	21.28
30	FRONT FENDER BRACE - RH	1	\$ 132.00		
31	FRONT FENDER BRACKET CENTER - RH	1	\$ 55.00		
32	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00		
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 149.00		
34	FRONT WHEEL SPOILER - RH	1	\$ 82.00	\$	65.12
35	FRONT WHEEL SPOILER LOWER - RH	1	\$ 40.00		
36	FRONT FENDER LEDGE COVER LONG - RH	1	\$ 35.00	\$	27.52
37	HEADLAMPS COVER - RH	1	\$ 49.00	\$	38.64
38	BONNET	1	\$ 3,425.00	\$	2,740.00
39	BONNET ATTACHMENT PARTS	1	\$ 431.00		
40	BONNET HINGE - LH / RH	2	\$ 680.00		
SUB TOTAL SPARE PARTS		:	\$ 7,751.00	\$	8,406.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	
41	BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$	93.00	\$ 8,406.00
42	BONNET STRIKER - LH / RH	2	\$	112.00	73.20
43	BONNET LOCK	2	\$	455.00	
44	BONNET BOWDEN CABLE - CENTER	1	\$	64.00	
45	BONNET BOWDEN CABLE - OUTER	1	\$	64.00	
46	BONNET RELEASE CABLE COVER	1	\$	11.00	
47	BONNET RELEASE LEVER	1	\$	15.00	
48	BONNET LOCK CABLE	1	\$	82.00	
49	BONNET PLENUM CHAMBER	1	\$	108.00	
50	HEADLIGHT - RH	1	\$	8,172.00	\$ 6,537.60
51	SPACER	3	\$	136.00	
52	HEADLIGHT HOSE	1	\$	42.00	
53	LIFT CYLINDER - RH	1	\$	231.00	
54	LIFT CYLINDER BRACKET	1	\$	7.00	\$ 5.44
55	LIFT CYLINDER CORRUGATED PIPE	1	\$	107.00	
56	LOCK CARRIER	1	\$	1,127.00	
57	LOCK CARRIER SUPPORT	1	\$	43.00	
58	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	21.00	\$ 16.32
59	A/C CONDENSER	1	\$	683.00	
60	CHARGE AIR COOLER	1	\$	654.00	
SUB TOTAL SPARE PARTS		:	\$	12,227.00	\$ 15,038.56

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f		\$ 15,038.56
61	CHARGE AIR COOLER PRESSURE HOSE - RH	1	\$ 413.00	
62	RADIATOR AIR GUIDE INNER - RH	1	\$ 51.00	\$ 40.08
63	RADIATOR AIR GUIDE OUTER - RH	1	\$ 19.00	\$ 14.64
64	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	
65	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00	
66	RADIATOR AIR GUIDE OUTER - LH	1	\$ 19.00	
67	RADIATOR COOLANT	6	\$ 282.00	
68	NOISE INSULATION	1	\$ 640.00	
69	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
70	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 29,642.00	\$ 15,153.28
TOTAL LABOUR CHARGES		:	\$ 12,412.00	\$ 4,962.00
GRAND TOTAL		:	\$ 42,054.00	\$ 20,115.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-05/12/22



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0514/2022/JT 12-Jul-22 Kee Siang 1 of 1 SLL 4664 C AUDI A4 2.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REAPPLY PAINT PROTECTION	\$ 890.00	\$ 890.00
GRAND TOTAL		\$ 890.00	\$ 890.00

For Premium Automobiles Pte Ltd

Authorised Signature