

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0514/2022/JT
DATE : 22-Jun-22
WIP : 29668

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAM JIA CONG, WILSON
ADDRESS : BLK 213 MARSILING CRESCENT
#12-61
SINGAPORE 730213
TELEPHONE : HP +65 98284283
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070162902
VEHICLE NO : **SLL 4664 C**
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 25/11/2020
ENGINE NO : DEM 026778
CHASSIS NO : WAUZZZF43MA012023
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-22
PLACE OF ACCIDENT : TAMPINES AVE 1

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 4664 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,400.00 X	
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 X	
5	TO DIMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 1800	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER.	\$ 3,000.00 1650	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 11,522.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Delivered</i>	1	\$ 2,377.00 ✓		1901.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 393.00 X		
3	FRONT BUMPER SECURING STRIP <i>NN</i>	2	\$ 79.00 X		
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 219.00 ✓		174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>cracked</i>	1	\$ 293.00 ✓		234.00
6	FRONT BUMPER AIR GUIDE - RH <i>NN</i>	1	\$ 51.00 X		
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>cracked</i>	1	\$ 293.00 ✓		234.00
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>ut</i>	1	\$ 151.00 ✓		120.140
9	FRONT BUMPER TRIM - RH <i>Prod.</i>	1	\$ 54.00 ✓		42.64
10	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,754.00 ✓		1403.20
11	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 212.00 ✓		169.20
12	FRONT BUMPER REINFORCEMENT BEAM <i>NN</i>	1	\$ 899.00 X		
13	FRONT BUMPER GUIDE SECTION - RH <i>new cracked</i>	1	\$ 41.00 * ✓		32.24
14	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00 X		
15	CAUTION STICKER <i>NN</i>	1	\$ 16.00 X		
16	AIR COND STICKER <i>NN</i>	1	\$ 9.00 X		
17	FRONT BUMPER BRACKET LOCK CARRIER <i>cracked</i>	1	\$ 154.00 ✓		122.80
18	FRONT BUMPER SUPPORT - LH / RH <i>NN</i>	2	\$ 64.00 X		
19	FRONT BUMPER POP RIVET <i>NN</i>	4	\$ 4.00 X		
20	FRONT PARKING AID SENSOR - INNER / OUTER <i>NP</i>	2	\$ 530.00 X		
SUB TOTAL SPARE PARTS		:	\$ 7,736.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR SEAL RING <i>3 new</i>	4	\$ 10.00	+
22	FRONT BUMPER WIRING SET	1	\$ 642.00	+
23	HORN - RH <i>3 new</i>	1	\$ 139.00	+
24	HORN SUPPORT- RH	1	\$ 33.00	+
25	FRONT FENDER - RH <i>not new Buckled</i>	1	\$ 1,227.00	✓ 981.60
26	FRONT FENDER ATTACHMENT PARTS - RH <i>new</i>	1	\$ 211.00	+
27	FRONT FENDER CLOSING ELEMENT - RH <i>3 damaged.</i>	1	\$ 81.00	✓ 64.24
28	FRONT FENDER BRACKET - RH	1	\$ 41.00	✓ 32.72
29	FRONT FENDER POP RIVET <i>new</i>	7	\$ 27.00	✓ 21.28
30	FRONT FENDER BRACE - RH	1	\$ 132.00	+
31	FRONT FENDER BRACKET CENTER - RH <i>3 new</i>	1	\$ 55.00	+
32	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	+
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 149.00	+
34	FRONT WHEEL SPOILER - RH <i>Delivered</i>	1	\$ 82.00	✓ 65.12
35	FRONT WHEEL SPOILER LOWER - RH <i>NN</i>	1	\$ 40.00	+
36	FRONT FENDER LEDGE COVER LONG - RH <i>new d.</i>	1	\$ 35.00	✓ 27.52
37	HEADLAMPS COVER - RH <i>new cracked</i>	1	\$ 49.00	✓ 38.64
38	BONNET <i>Delivered</i>	1	\$ 3,425.00	✓ 2740.00
39	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 431.00	+
40	BONNET HINGE - LH / RH <i>new</i>	2	\$ 680.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,751.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>nee</i>	3	\$ 93.00 <i>+</i> ✓	73.20
42	BONNET STRIKER - LH / RH <i>nee</i>	2	\$ 112.00 <i>+</i>	
43	BONNET LOCK <i>Not nee</i>	2	\$ 455.00 <i>+</i>	
44	BONNET BOWDEN CABLE - CENTER <i>?</i>	1	\$ 64.00 <i>+</i>	
45	BONNET BOWDEN CABLE - OUTER	1	\$ 64.00 <i>X</i>	
46	BONNET RELEASE CABLE COVER <i>Not nee</i>	1	\$ 11.00 <i>X</i>	
47	BONNET RELEASE LEVER <i>nee</i>	1	\$ 15.00 <i>X</i>	
48	BONNET LOCK CABLE	1	\$ 82.00 <i>+</i>	
49	BONNET PLENUM CHAMBER	1	\$ 108.00 <i>+</i>	
50	HEADLIGHT - RH <i>cut</i>	1	\$ 8,172.00 <i>✓</i>	6537.60
51	SPACER <i>Not nee</i>	3	\$ 136.00 <i>+</i>	
52	HEADLIGHT HOSE	1	\$ 42.00 <i>+</i>	
53	LIFT CYLINDER - RH <i>Not nee</i>	1	\$ 231.00 <i>+</i>	
54	LIFT CYLINDER BRACKET <i>Damaged</i>	1	\$ 7.00 <i>+</i> ✓	3.44
55	LIFT CYLINDER CORRUGATED PIPE <i>Not nee</i>	1	\$ 107.00 <i>+</i>	
56	LOCK CARRIER <i>Not nee</i>	1	\$ 1,127.00 <i>+</i>	
57	LOCK CARRIER SUPPORT <i>nee</i>	1	\$ 43.00 <i>+</i>	
58	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Damaged</i>	1	\$ 21.00 <i>+</i> ✓	16.32
59	A/C CONDENSER <i>Not nee</i>	1	\$ 683.00 <i>+</i>	
60	CHARGE AIR COOLER	1	\$ 654.00 <i>+</i>	
SUB TOTAL SPARE PARTS		:	\$ 12,227.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	CHARGE AIR COOLER PRESSURE HOSE - RH <i>NN</i>	1	\$ 413.00 <i>X</i>	
62	RADIATOR AIR GUIDE INNER - RH <i>torn</i>	1	\$ 51.00 <i>X</i> ✓	40.08
63	RADIATOR AIR GUIDE OUTER - RH <i>XHP</i>	1	\$ 19.00 <i>X</i> ✓	14.64
64	RADIATOR AIR GUIDE - UPPER <i>rec</i>	1	\$ 19.00 <i>X</i>	
65	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00 <i>X</i>	
66	RADIATOR AIR GUIDE OUTER - LH	1	\$ 19.00 <i>X</i>	
67	RADIATOR COOLANT <i>XHP Ne</i>	6	\$ 282.00 <i>X</i>	
68	NOISE INSULATION	1	\$ 640.00 <i>X</i>	
69	FRONT NO PLATE <i>Rec</i>	S/N	\$ 60.00 ✓	60.00
70	SUNDRIES <i>NN</i>		\$ 400.00 <i>X</i>	
TOTAL SPARE PARTS		:	\$ 29,642.00	
TOTAL LABOUR CHARGES		:	\$ 11,522.00	
GRAND TOTAL		:	\$ 41,164.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan King
SURVEYED DATE : 23/06/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 0 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Celine / Hui Rong .

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0514/2022/JT 12-Jul-22 Kee Siang 1 of 1 SLL 4664 C AUDI A4 2.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
Labours			
1	TO REAPPLY PAINT PROTECTION	\$ 890.00	✓
GRAND TOTAL		\$ 890.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian L
[Signature]