

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0514/2022/JT
DATE : 22-Jun-22
WIP : 29668

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAM JIA CONG, WILSON
ADDRESS : BLK 213 MARSILING CRESCENT
#12-61
SINGAPORE 730213
TELEPHONE : HP +65 98284283
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070162902
VEHICLE NO : SLL 4664 C
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 25/11/2020
ENGINE NO : DEM 026778
CHASSIS NO : WAUZZZF43MA012023
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jun-22
PLACE OF ACCIDENT : TAMPINES AVE 1

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 4664 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,400.00	x
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	x.
5	TO DIMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	1800
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER.	\$ 3,000.00	1650
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,522.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehmd</i>	1	\$ 2,377.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 393.00	X
3	FRONT BUMPER SECURING STRIP ?	2	\$ 79.00	?
4	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$ 219.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER ?	1	\$ 293.00	?
6	FRONT BUMPER AIR GUIDE - RH ?	1	\$ 51.00	?
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER ?	1	\$ 293.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i>	1	\$ 151.00	✓
9	FRONT BUMPER TRIM - RH <i>Rehmd</i>	1	\$ 54.00	✓
10	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,754.00	✓
11	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 212.00	?
12	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 899.00	?
13	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 41.00	X
14	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00	X
15	CAUTION STICKER ?	1	\$ 16.00	?
16	AIR COND STICKER ?	1	\$ 9.00	?
17	FRONT BUMPER BRACKET LOCK CARRIER ?	1	\$ 154.00	?
18	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 64.00	?
19	FRONT BUMPER POP RIVET <i>new</i>	4	\$ 4.00	✓
20	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 530.00	X
SUB TOTAL SPARE PARTS			\$ 7,736.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	+
22	FRONT BUMPER WIRING SET	1	\$ 642.00	+
23	HORN - RH	1	\$ 139.00	+
24	HORN SUPPORT- RH	1	\$ 33.00	+
25	FRONT FENDER - RH	1	\$ 1,227.00	+
26	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 211.00	+
27	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	+
28	FRONT FENDER BRACKET - RH	1	\$ 41.00	+
29	FRONT FENDER POP RIVET	7	\$ 27.00	+
30	FRONT FENDER BRACE - RH	1	\$ 132.00	+
31	FRONT FENDER BRACKET CENTER - RH	1	\$ 55.00	+
32	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	+
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 149.00	+
34	FRONT WHEEL SPOILER - RH	1	\$ 82.00	+
35	FRONT WHEEL SPOILER LOWER - RH	1	\$ 40.00	+
36	FRONT FENDER LEDGE COVER LONG - RH	1	\$ 35.00	+
37	HEADLAMPS COVER - RH	1	\$ 49.00	+
38	BONNET	1	\$ 3,425.00	+
39	BONNET ATTACHMENT PARTS	1	\$ 431.00	+
40	BONNET HINGE - LH / RH	2	\$ 680.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,751.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>3 not ne</i>	3	\$ 93.00	+
42	BONNET STRIKER - LH / RH	2	\$ 112.00	+
43	BONNET LOCK <i>Not ne</i>	2	\$ 455.00	+
44	BONNET BOWDEN CABLE - CENTER <i>3 not ne</i>	1	\$ 64.00	+
45	BONNET BOWDEN CABLE - OUTER	1	\$ 64.00	X
46	BONNET RELEASE CABLE COVER <i>Not ne</i>	1	\$ 11.00	X
47	BONNET RELEASE LEVER <i>Not ne</i>	1	\$ 15.00	X
48	BONNET LOCK CABLE	1	\$ 82.00	+
49	BONNET PLENUM CHAMBER	1	\$ 108.00	+
50	HEADLIGHT - RH <i>Cut</i>	1	\$ 8,172.00	✓
51	SPACER <i>3 not ne</i>	3	\$ 136.00	+
52	HEADLIGHT HOSE	1	\$ 42.00	+
53	LIFT CYLINDER - RH <i>3 not ne</i>	1	\$ 231.00	+
54	LIFT CYLINDER BRACKET <i>3 not ne</i>	1	\$ 7.00	+
55	LIFT CYLINDER CORRUGATED PIPE <i>Not ne</i>	1	\$ 107.00	+
56	LOCK CARRIER <i>3 not ne</i>	1	\$ 1,127.00	+
57	LOCK CARRIER SUPPORT <i>3 not ne</i>	1	\$ 43.00	+
58	OUTSIDE TEMPERATURE SENSOR BRACKET <i>3 not ne</i>	1	\$ 21.00	+
59	A/C CONDENSER	1	\$ 683.00	+
60	CHARGE AIR COOLER	1	\$ 654.00	+
SUB TOTAL SPARE PARTS		:	\$ 12,227.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 4664 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	CHARGE AIR COOLER PRESSURE HOSE - RH	1	\$ 413.00	X
62	RADIATOR AIR GUIDE INNER - RH	1	\$ 51.00	X
63	RADIATOR AIR GUIDE OUTER - RH	1	\$ 19.00	X
64	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	X
65	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00	X
66	RADIATOR AIR GUIDE OUTER - LH	1	\$ 19.00	X
67	RADIATOR COOLANT	6	\$ 282.00	X
68	NOISE INSULATION	1	\$ 640.00	X
69	FRONT NO PLATE	S/N	\$ 60.00	✓
70	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 29,642.00	
TOTAL LABOUR CHARGES		:	\$ 11,522.00	
GRAND TOTAL		:	\$ 41,164.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *23/06/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 0\$ Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT