

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/499/2022/JT
DATE : 16-Jun-22
WIP : 28952

Xiao Chen.

15 Days.

\$28141.24.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/06/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. TAN SIK CHYE
ADDRESS : BLK 22 CHOACHU KANG ST 64
#06-04
SINGAPORE 689094
TELEPHONE : HP +65 98320878
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100501630-05
VEHICLE NO : SLL 5271 X
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 28/2/2017
ENGINE NO : CYG 017811
CHASSIS NO : WAUZZZ4G5HN064989
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jun-22
PLACE OF ACCIDENT : TUAS CHECKPOINT AFTER CUSTOM

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 5271 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N S	360.00	✓✓
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N S	600.00	✓✓
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS	S/N S	200.00	150 ✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N S	400.00	K. ✓✓
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N S	1,600.00	✓✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N S	1,600.00	✓✓
SUB-TOTAL LABOUR CHARGES		:	\$ 4,760.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 5271 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	560 ✓
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 8,000.00	4000 ✓
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANEL LINING	88% \$ 3875 8,000.00	Fender : 3.5 x 550 = 1925 Bumper : 550 Handle x 2 = 200 Mirror = 100
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 21,752.00	

2775.



S5 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 5271 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1	S 3,475.00	+
2	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	S 60.00	+
3	REAR FENDER - LH <i>Dented</i>	1	S 4,870.00	✓ 3896
4	REAR WINDSCREEN <i>3 new</i>	1	S 1,307.00	✓ 1045.60
5	QUARTER WINDOW - LH	1	S 434.00	✓ 346.80
6	PRIMER <i>new</i>	2	S 44.00	✓ 34.72
7	REAR SILL TRIM STRIP - LH <i>new</i>	1	S 133.00	✓ 106 ✓
8	SIDE MEMBER TRIM - LH <i>new</i>	1	S 905.00	+
9	SILL PANEL CLIP ATTACHMENT PARTS <i>new</i>	1	S 93.00	✓ 74.24 ✓
10	SILL PANEL ADHESIVE TAPES <i>new</i>	1	S 18.00	✓ 14.24
11	REAR BUMPER STONE CHIP GUARD - LH <i>new</i>	1	S 133.00	?
12	REAR WHEEL HOUSING LINER - LH <i>new</i>	1	S 299.00	+
13	REAR DOOR - LH <i>Dented</i>	1	S 4,760.00	✓ 3808
14	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	S 88.00	+
15	REAR DOOR OUTER SEAL - LH <i>new</i>	1	S 256.00	✓ 204.80
16	BONDING AGENT <i>3 new</i>	1	S 51.00	?
17	CLEANING SOLUTION <i>new</i>	1	S 74.00	?
18	APPLICATOR <i>new</i>	1	S 8.00	?
19	REAR DOOR SEAL, OUTER - LH <i>new</i>	1	S 322.00	+
20	REAR DOOR CATCH - LH <i>new</i>	1	S 134.00	?
SUB TOTAL SPARE PARTS		:	\$ 17,464.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 5271 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT DOOR - LH <i>Dented</i>	1	\$ 4,760.00	✓ 3808
22	FRONT DOOR STONE GUARD FILM - LH <i>new</i>	1	\$ 135.00	✓ 108
23	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 199.00	+
24	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$ 256.00	✓ 204.80
25	BONDING AGENT <i>new</i>	1	\$ 51.00	? X
26	CLEANING SOLUTION <i>new</i>	1	\$ 74.00	? X
27	APPLICATOR <i>new</i>	1	\$ 8.00	? X
28	FRONT DOOR CATCH - LH <i>Not Nec.</i>	1	TBC	?
29	WING MIRROR MOUNTING - LH <i>new</i>	1	\$ 1,552.00	+
30	WING MIRROR HOUSING - LH <i>Repair</i>	1	\$ 221.00	+
31	TURN SIGNAL INDICATOR <i>new</i>	1	\$ 141.00	+
32	WING MIRROR GLASS - LH <i>new</i>	1	\$ 1,298.00	+
33	FRONT DOOR HANDLE, EXTERIOR - LH <i>Repair</i>	1	\$ 651.00	+
34	FRONT DOOR CAP - PASSENGER DOOR <i>Repair</i>	1	\$ 129.00	+
35	ARYLIC SEALANT <i>Nec</i>	S/N	\$ 180.00	✓
36	CAVITY WAX	S/N	\$ 140.00	✓
37	STONE CHIP	S/N	\$ 180.00	✓
38	METAL FILLER POWDER	S/N	\$ 280.00	✓
39	1/4 GLASS SEALANT	S/N	\$ 100.00	✓
40	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	✓
41	SUNDRIES <i>Nec</i>		\$ 400.00	? 40.64 ✓
TOTAL SPARE PARTS		:	\$ 28,419.00	
TOTAL LABOUR CHARGES		:	\$ 21,752.00	
GRAND TOTAL		:	\$ 50,171.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian G.
23/06/22.

Not Authorised, 15 Days. 

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: