

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 5271 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00	\$ 600.00
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS	S/N \$	200.00	\$ 150.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00	\$ 400.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	\$ 1,600.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	\$ 1,600.00
SUB-TOTAL LABOUR CHARGES		:	\$ 4,760.00	\$ 4,710.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 5271 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		C/F		\$ 4,710.00
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	\$ 560.00
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	8,000.00	\$ 4,000.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$	8,000.00	\$ 3,875.00
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 21,752.00	\$ 13,337.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 5271 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,475.00	
2	REAR BUMPER GUIDE SECTION - LH	1	\$ 60.00	
3	REAR FENDER - LH	1	\$ 4,870.00	\$ 3,896.00
4	REAR WINDSCREEN	1	\$ 1,307.00	\$ 1,045.60
5	QUARTER WINDOW - LH	1	\$ 434.00	\$ 346.80
6	PRIMER	2	\$ 44.00	\$ 34.72
7	REAR SILL TRIM STRIP - LH	1	\$ 133.00	\$ 106.00
8	SIDE MEMBER TRIM - LH	1	\$ 905.00	
9	SILL PANEL CLIP ATTACHMENT PARTS	1	\$ 93.00	\$ 74.24
10	SILL PANEL ADHESIVE TAPES	1	\$ 18.00	\$ 14.24
11	REAR BUMPER STONE CHIP GUARD - LH	1	\$ 133.00	
12	REAR WHEEL HOUSING LINER - LH	1	\$ 299.00	
13	REAR DOOR - LH	1	\$ 4,760.00	\$ 3,808.00
14	REAR DOOR ATTACHMENT PARTS	1	\$ 88.00	
15	REAR DOOR OUTER SEAL - LH	1	\$ 256.00	\$ 204.80
16	BONDING AGENT	1	\$ 51.00	
17	CLEANING SOLUTION	1	\$ 74.00	
18	APPLICATOR	1	\$ 8.00	
19	REAR DOOR SEAL, OUTER - LH	1	\$ 322.00	
20	REAR DOOR CATCH - LH	1	\$ 134.00	
SUB TOTAL SPARE PARTS			\$ 17,464.00	\$ 9,530.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 5271 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	9,530.40
21	FRONT DOOR - LH	1	\$ 4,760.00	\$	3,808.00
22	FRONT DOOR STONE GUARD FILM - LH	1	\$ 135.00	\$	108.00
23	FRONT DOOR ATTACHMENT PARTS	1	\$ 199.00		
24	FRONT DOOR OUTER SEAL - LH	1	\$ 256.00	\$	204.80
25	BONDING AGENT	1	\$ 51.00		
26	CLEANING SOLUTION	1	\$ 74.00		
27	APPLICATOR	1	\$ 8.00		
28	FRONT DOOR CATCH - LH	1	TBC		
29	WING MIRROR MOUNTING - LH	1	\$ 1,552.00		
30	WING MIRROR HOUSING - LH	1	\$ 221.00		
31	TURN SIGNAL INDICATOR	1	\$ 141.00		
32	WING MIRROR GLASS - LH	1	\$ 1,298.00		
33	FRONT DOOR HANDLE, EXTERIOR - LH	1	\$ 651.00		
34	FRONT DOOR CAP - PASSENGER DOOR	1	\$ 129.00		
35	ARYLIC SEALANT	S/N	\$ 180.00	\$	180.00
36	CAVITY WAX	S/N	\$ 140.00	\$	140.00
37	STONE CHIP	S/N	\$ 180.00	\$	180.00
38	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
39	1/4 GLASS SEALANT	S/N	\$ 100.00	\$	100.00
40	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$	200.00
41	Added parts - see attached		\$ 41.00	\$	32.40
42	SUNDRIES		\$ 400.00	\$	40.64
TOTAL SPARE PARTS			\$ 28,460.00	\$	14,804.24
TOTAL LABOUR CHARGES			\$ 21,752.00	\$	13,337.00
GRAND TOTAL			\$ 50,212.00	\$	28,141.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-07/09/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/499/2022/JT 6-Aug-22 CHANG 1 of 1 SLL 5271 X AUDI A6 1.8 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	CLIP SET FOR CHROME TRIM	\$ 41.00	\$	32.40
	GRAND TOTAL	\$ 41.00	\$	32.40

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/499/2022/JT
DATE : 16-Jun-22
WIP : 28952

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/06/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

15 days exclude 2 Sundays & 1 PH

Hohnny Boo 26 Sep 22

OWNER'S NAME : MR. TAN SIK CHYE
ADDRESS : BLK 22 CHO A CHU KANG ST 64
#06-04
SINGAPORE 689094
TELEPHONE : HP +65 98320878
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100501630-05
VEHICLE NO : **SLL 5271 X**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 28/2/2017
ENGINE NO : CYG 017811
CHASSIS NO : WAUZZZ4G5HN064989
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jun-22
PLACE OF ACCIDENT : TUAS CHECKPOINT AFTER CUSTOM