

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Xiao Chen

Supplementary Estimate-1

GST Reg No. 19-9902271-W


AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/499/2022/JT
6-Aug-22
CHANG
1 of 1
SLL 5271 X
AUDI A6 1.8 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	CLIP SET FOR CHROME TRIM <i>new</i>	\$ 41.00	✓ 32.40
GRAND TOTAL		\$ 41.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling
S/S. Remmyed.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 5271 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00 560.	
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 8,000.00 4000.	
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR FEND PANEL TRIM.	\$ 8,000.00	
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ <u>21,752.00</u>	

Fender : 3.5 x 550
 = 1925

Bumper : 550

Handle x 2 = 200

Mirror = 100

2775.

+
 2x door = 1100

[Signature]

Car in

29/7/22

wip: 28952

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

 Kam/Hong 

AIG - Adrian

- 15 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 5271 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>Repair</i>	1	\$	3,475.00	+
2	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$	60.00	+
3	REAR FENDER - LH <i>Dented</i>	1	\$	4,870.00	✓
4	REAR WINDSCREEN <i>3 new</i>	1	\$	1,307.00	✓
5	QUARTER WINDOW - LH	1	\$	434.00	-
6	PRIMER <i>new</i>	2	\$	44.00	-
7	REAR SILL TRIM STRIP - LH <i>new</i>	1	\$	133.00	✓ <i>H/S</i>
8	SIDE MEMBER TRIM - LH <i>Not new</i>	1	\$	905.00	+
9	SILL PANEL CLIP ATTACHMENT PARTS <i>new</i>	1	\$	93.00	✓ <i>H/S</i>
10	SILL PANEL ADHESIVE TAPES <i>new</i>	1	\$	18.00	-
11	REAR BUMPER STONE CHIP GUARD - LH ?	1	\$	133.00	?
12	REAR WHEEL HOUSING LINER - LH <i>new</i>	1	\$	299.00	+
13	REAR DOOR - LH <i>Dented</i>	1	\$	4,760.00	✓
14	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$	88.00	+
15	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$	256.00	✓
16	BONDING AGENT ?	1	\$	51.00	?
17	CLEANING SOLUTION ?	1	\$	74.00	?
18	APPLICATOR ?	1	\$	8.00	?
19	REAR DOOR SEAL, OUTER - LH <i>new</i>	1	\$	322.00	+
20	REAR DOOR CATCH - LH ?	1	\$	134.00	?
SUB TOTAL SPARE PARTS		:	\$	17,464.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (DI) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.