



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301397

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 09/03/2023  
Reference CC6/CTI22006025/Aya3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SLU 601M  
Insured Veh. GBF 5126H  
Claim No. SNM22D204353  
Policy No. DMCVSNW00139092103  
Accident Date 20/06/2022  
Inspection Date 23/06/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                              |                                                                                                                                        |                                                                       |                                                              |                       |
|------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|--------------------------------------------------------------|-----------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909 |                                                                                                                                        |                                                                       | Ref: CC6/CTI22006025/Aya3q2<br>Date: 09/03/2023<br>Code: CTI |                       |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                              |                                                                                                                                        |                                                                       |                                                              |                       |
|                                                                                                | Insured Veh.                                                                                                                           | GBF 5126H                                                             | Veh. Inspected                                               | SLU 601M              |
|                                                                                                | Policy No.                                                                                                                             | DMCVSNW00139092103                                                    | Coverage (\$)                                                | 0.00                  |
|                                                                                                | Claim No.                                                                                                                              | SNM22D204353                                                          | Excess (\$)                                                  | 0.00                  |
|                                                                                                | Assign From                                                                                                                            |                                                                       | Assign Date                                                  | 23/06/2022            |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                  |                                                                                                                                        |                                                                       |                                                              |                       |
|                                                                                                | Make & Model                                                                                                                           | B.M.W. 216I GT                                                        | c.c                                                          | 1499                  |
|                                                                                                | Engine No.                                                                                                                             | HIDDEN                                                                | Year of Reg.                                                 | 2017                  |
|                                                                                                | Chassis No.                                                                                                                            | WBA2D920805E91631                                                     | Colour                                                       | RED                   |
|                                                                                                | Odometer                                                                                                                               | 53226 KM                                                              | Steering                                                     | IN ORDER              |
|                                                                                                | Brakes                                                                                                                                 | IN ORDER                                                              | Modification                                                 | SPORTS RIM            |
|                                                                                                | General                                                                                                                                | GOOD                                                                  |                                                              |                       |
| <b>3. Conditions of Tyres</b>                                                                  |                                                                                                                                        |                                                                       |                                                              |                       |
|                                                                                                |                                                                                                                                        | Size                                                                  | Make                                                         | Balance               |
|                                                                                                | R/H Front Tyre                                                                                                                         | 205/60 R16                                                            | PIRELLI                                                      | 6 mm                  |
|                                                                                                | L/H Front Tyre                                                                                                                         | 205/60 R16                                                            | PIRELLI                                                      | 6 mm                  |
|                                                                                                | R/H Rear Tyre                                                                                                                          | 205/60 R16                                                            | PIRELLI                                                      | 6 mm                  |
|                                                                                                | L/H Rear Tyre                                                                                                                          | 205/60 R16                                                            | PIRELLI                                                      | 6 mm                  |
| <b>4. Description of Damages</b>                                                               |                                                                                                                                        |                                                                       |                                                              |                       |
|                                                                                                | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br><br>DAMAGES SEE DETAILS.                                                    |                                                                       |                                                              |                       |
| <b>5. General Information</b>                                                                  |                                                                                                                                        |                                                                       |                                                              |                       |
|                                                                                                | Accident Date                                                                                                                          | 20/06/2022                                                            | Inspection Date                                              | 23/06/2022            |
|                                                                                                | Survey held at                                                                                                                         | SM AUTOMOTIVE<br>BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883 |                                                              |                       |
| <b>5a. Remarks</b>                                                                             |                                                                                                                                        |                                                                       |                                                              |                       |
|                                                                                                | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                       |                                                              |                       |
| <b>5b. Estimate Days of Repair</b>                                                             |                                                                                                                                        |                                                                       |                                                              |                       |
|                                                                                                | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                       |                                                              | <b>4 Working Days</b> |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 601M

| Qty                                | Description of Parts                                                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                                                                 |                      |                           |                   |
| 1                                  | FRONT BUMPER                                                                                    | DEFORMED             | 985.00                    | 985.00            |
| 1                                  | RH FRONT BUMPER SIDE RETAINER                                                                   | NOT NECESSARY        | 45.00                     | -                 |
| 1                                  | RH FRONT BUMPER FOG LAMP                                                                        | NOT NECESSARY        | 170.00                    | -                 |
| 1                                  | RH FRONT BUMPER FOG LAMP COVER                                                                  | NOT NECESSARY        | 68.00                     | -                 |
| 2                                  | RH FRONT BUMPER PARK SENSOR @\$65.00                                                            | NOT NECESSARY        | 130.00                    | -                 |
| 1                                  | RH FRONT BUMPER SIDE BRACKET                                                                    | NOT NECESSARY        | 65.00                     | -                 |
| 1                                  | RH FRONT HEADLAMP                                                                               | CRACKED              | 1,850.00                  | 1,850.00          |
| 1                                  | RH FRONT HEADLAMP LOWER BRACKET                                                                 | NOT NECESSARY        | 85.00                     | -                 |
| 1                                  | RH FRONT FENDER                                                                                 | TO REPAIR SEE LABOUR | 380.00                    | -                 |
| 1                                  | RH FRONT FENDER INNER SEAL                                                                      | NOT NECESSARY        | 125.00                    | -                 |
| 1                                  | RH FRONT MIRROR                                                                                 | DAMAGED              | 685.00                    | 685.00            |
| 1                                  | RH FRONT MIRROR COVER                                                                           | TO REPAIR SEE LABOUR | 146.00                    | -                 |
| 1                                  | RH FRONT MIRROR SIGNAL LAMP                                                                     | CRACKED              | 189.00                    | 189.00            |
|                                    | LESS 5% DISCOUNT                                                                                |                      | -246.15                   | -                 |
|                                    | LESS 10% DISCOUNT                                                                               |                      | -                         | -370.90           |
|                                    |                                                                                                 |                      | 4,676.85                  | 3,338.10          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                                                                 |                      |                           |                   |
| 1                                  | FRONT BUMPER CLIPS (SN)                                                                         | NECESSARY            | 80.00                     | 30.00             |
| 1                                  | RH FRONT SPORT RIM (SN)                                                                         | NOT NECESSARY        | 1,200.00                  | -                 |
| 1                                  | RH FRONT FENDER INNER SEAL CLIPS (SN)                                                           | NOT NECESSARY        | 60.00                     | -                 |
| 1                                  | RH FRONT TYRE (SN)                                                                              | NOT NECESSARY        | 350.00                    | -                 |
|                                    |                                                                                                 |                      | 1,690.00                  | 30.00             |
| <b><u>LABOUR</u></b>               |                                                                                                 |                      |                           |                   |
|                                    | TO CONDUCT WHEEL ALIGNMENT.                                                                     | NOT NECESSARY        | 150.00                    | -                 |
|                                    | LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF RH FRONT FENDER AND RH FRONT MIRROR COVER . |                      | 1,200.00                  | 400.00            |
|                                    | LABOUR FOR SPRAYPAINTING.                                                                       |                      | 900.00                    | 400.00            |
|                                    | WIRING CHECK .                                                                                  |                      | 80.00                     | 30.00             |

Report Ref No. CC6/CTI22006025/Aya3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|----------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS . | NOT NECESSARY | 300.00                    | -                 |
|                                                                             |                                                    |               | 2,630.00                  | 830.00            |
| <b>GRAND TOTAL</b>                                                          |                                                    |               | <b>8,996.85</b>           | <b>4,198.10</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                    |               |                           | <b>3,300.00</b>   |

Report Ref No. CC6/CTI22006025/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLU 601M

### INSPECTION






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 601M

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

