

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

23/06/2022

01-43

Singapore 417883

Accident date : 20/06/2022

Estimated repair cost for vehicle no: SLU601M BMW 216I GT LED

CHASSIS: WBA2D920805E91631 (2017)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Debond</i>	\$985.00	\$985.00 ✓
2	1	RH FRONT BUMPER SIDE RETAINER <i>He ne</i>	\$45.00	\$45.00 X
3	1	RH FRONT BUMPER FOG LAMP <i>2 NP</i>	\$170.00	\$170.00 X
4	1	RH FRONT BUMPER FOG LAMP COVER <i>He ne</i>	\$68.00	\$68.00 X
5	2	RH FRONT BUMPER PARK SENSOR <i>He ne</i>	\$65.00	\$130.00 X
6	1	RH FRONT BUMPER SIDE BRACKET <i>RH ne</i>	\$65.00	\$65.00 X
7	1	RH FRONT HEADLAMP <i>Brake</i>	\$1,850	\$1,850 ✓
8	1	RH FRONT HEADLAMP LOWER BRACKET <i>He ne</i>	\$85.00	\$85.00 X
9	1	RH FRONT FENDER <i>Repair</i>	\$380.00	\$380.00 X
10	1	RH FRONT FENDER INNER SEAL <i>He ne</i>	\$125.00	\$125.00 X
11	1	RH FRONT MIRROR <i>Debond</i>	\$685.00	\$685.00 ✓
12	1	RH FRONT MIRROR COVER <i>Repair</i>	\$146.00	\$146.00 X
13	1	RH FRONT MIRROR SIGNAL LAMP <i>Cracked</i>	\$189.00	\$189.00 ✓

TOTAL : \$4,288.00

LESS 5 % \$214.40

SUB-TOTAL : \$4,073.60

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>He ne</i>	\$80.00	\$80.00 30
2	1	RH FRONT SPORT RIM <i>He ne</i>	\$1,200.00	\$1,200.00 X
3	1	RH FRONT FENDER INNER SEAL CLIPS <i>He ne</i>	\$60.00	\$60.00 +
4	1	RH FRONT TYRE <i>He ne</i>	\$350.00	\$350.00 +

TOTAL: \$1,690.00

TOTAL PARTS : \$5,763.60

SLU601M BMW 216I

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 TO CONDUCT WHEEL ALIGNMENT

830

~~\$1,200.00~~ 4w
~~\$900.00~~ 4w
~~\$80.00~~ 30
\$300.00 X
\$150.00 X

Subtotal :- \$2,630.00

Total:- \$8,393.60

Adm L
2/5 23/06/22
04 Day.

Total: 4198400

1/s: 3.3k

3.3k.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: