

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notified
1/1/2022
Recovery After Policy
Today

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Accident Date : 01.06.2022

Date: 23.06.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Mazda 3" Reg. No. SND1473A Claiming Against Your Insured Veh. No. SLU5458C		
1pc	Front Bumper	3.50	1,035.00 X
14pcs	Front Bumper Clips		49.00 X
1pc	Headlamp RH		873.00 X
1pc	Front Fender RH		382.00
1pc	Front Fender Shield	4.00	141.00
8pcs	Front Fender Shield Clips		32.00
1pc	Front Fender Inner Vertical Shield (Sponge)		189.00
1pc	Front Door RH		1,295.00
1pc	Front Door Lower Hinge		46.00
1pc	Front Door Arrester		157.00
1pc	Front Door Weatherstrip		125.00
1pc	Front Door Sticker		136.00
12pcs	Front Door Inner Trim Board Clips	5.50	66.00 X
1pc	Front Door Wing Mirror RH		690.00 X
1pc	Rear Door RH		1,100.00
1pc	Rear Door Lower Hinge		46.00 X
1pc	Rear Door Arrester		157.00 X
1pc	Rear Door Sticker		136.00
12pcs	Rear Door Inner Trim Board Clips	5.50	66.00 X
1pc	Rear Door Weatherstrip		125.00 X
1pc	Rocker Panel		924.00
1pc	Rocker Panel Chip Resistant Sticker		85.00
1pc	Rear Fender Splash Sticker		45.00 X
1pc	Rear Bumper	3.50	1,128.60 X
14pcs	Rear Bumper Clips		49.00 X
			9,077.60
	Less 20%		1,815.52
			7,262.08
	To Conduct Electrical Check		30.00 201
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		240.00 1201
	To Supply End Panel Body Sealant		60.00 301
	To Conduct Computerize Wheel Alignment Test		80.00 X
	To Conduct High Speed Balancing		80.00 X
		C/F	7,752.08

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Accident Date : 01.06.2022

Policy No: Third Party

Date: 23.06.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Mazda 3" Reg. No. SND1473A Claiming Against Your Insured Veh. No. SLU5458C		
		B/F	7,752.08
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 <i>900</i>
	To Repair / Respray Wheel Rim x2	150.00	<i>na</i> 300.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Rocker Inner Panel, Floor Panel, Door "B" Pillar, Rear Fender, Bumper.Cnt, Weld Rocker Panel & Part Replacement		800.00 <i>700</i>
	To Spray Painting Affected Areas (Large Veh) (Front Bumper, Rear Bumper, Door x2 (Inner / Outer), Wing Mirror, Front Fender, Rear Fender, Pillar, Rocker Panel)		<i>1200</i> 2,200.00
	To Reseal Paint Protection (Diamond rite) to Spray Paint Areas		<i>(Bill)</i> 1,200.00 <i>?</i>
	Total :		<u>12,402.08</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: