

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0515/2022/JT
DATE : 22-Jun-22
WIP : 29875

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WANG TAO
ADDRESS : 33 YISHUN ST 51
#08-26
SINGAPORE 767991
TELEPHONE : HP +65 98006481
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220057330
VEHICLE NO : SLW 1306 Z
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 28/5/2022
ENGINE NO : DEM 034245
CHASSIS NO : WAUZZF56MA062407
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Jun-22
PLACE OF ACCIDENT : ANG MO KIO AVE 3 UNDER FLYOVER AT CTE



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 1306 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N S	360.00 /	
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N S	300.00 /	
3	TO CARRY OUT WATER SEEPAGE FOR 1/4 GLASS.	S/N S	200.00 150	
4	TO INSTALL SOLAR FILM FOR 1/4 GLASS AND RHS REAR DOOR WINDOW GLASS.	S/N S	400.00 /	
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N S	1,600.00 /	(photo)
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN ETC.	S/N S	1,600.00 /	(photo)
SUB TOTAL LABOUR CHARGES			\$ 4,460.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 1306 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 /
8	TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	X
9	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER, RHS REAR BOTTOM PLATE, RHS OUTER WHEEL HOUSING WITH CONNECTING PLATE AND RHS SIDE PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 11,000.00	3500 4500 7 x 300
10	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, RHS SILL PANEL TRIM. RHS OUTER WHEEL HOUSING, BOTTOM PLATE, RHS SIDE PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$ 9,000.00	3425 3575 5.5 x 550
11	TO RENEW RHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	289
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		\$ 27,972.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 1306 Z

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	REAR BUMPER / <i>DD</i>	1	\$		2,609.00 /	2087.20
2	REAR BUMPER GUIDE SECTION - LH / RH ? <i>X nn</i>	2	\$		75.00	
3	TAIL LIGHT OUTER - RH <i>X nn</i>	1	\$		1,269.00	
4	REAR FENDER - RH / <i>DD</i>	1	\$		4,076.00 /	3260.80
5	QUARTER WINDOW - RH / <i>acc</i>	1	\$		798.00 /	638
6	PRIMER / <i>nc</i>	1	\$		22.00 /	17.36
7	FUEL INSERT / <i>acc</i>	1	\$		100.00 /	79.28
8	FUEL FILLER FLAP / <i>cut</i>	1	\$		343.00 /	274
9	REAR FENDER WHEEL HOUSING - RH OUTER <i>acc</i>	1	\$ <i>DD</i>		715.00 /	571.60
10	REAR FENDER INNER - RH <i>acc X nn</i>	1	\$		1,332.00	
11	REAR VENT TRIM <i>acc X nn</i>	1	\$		75.00	
12	BOTTOM PLATE - RH OUTER <i>acc X nn</i>	1	\$		506.00	
13	ACTIVATED CHARCOAL CONTAINER <i>acc X nn</i>	1	\$		647.00	
14	ACTIVATED CHARCOAL CONTAINER BRACKET <i>acc X nn</i>	1	\$		123.00	
15	REAR DOOR - RH / <i>DD</i>	1	\$		3,977.00 /	3181.60
16	REAR DOOR OUTER SEAL - RH / <i>acc</i>	1	\$		247.00 /	197.20
17	BONDING AGENT <i>acc X nn</i>	1	\$		51.00	
18	CLEANING SOLUTION <i>acc X nn</i>	1	\$		74.00	
19	APPLICATOR <i>acc X nn</i>	1	\$		8.00	
20	REAR DOOR ATTACHMENT PARTS <i>acc X nn</i>	1	\$		180.00	
SUB TOTAL SPARE PARTS					\$	17,227.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 1306 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR DOOR CATCH - RH ? X nn	1	\$	134.00	
22	REAR DOOR HANDLE TRIM PLATE - RH ? X nn	1	\$	98.00	
23	REAR DOOR HANDLE COVER - RH ? X nn	1	\$	7.00	
24	REAR DOOR HANDLE HOUSING - RH ? X nn	1	\$	9.00	
25	REAR DOOR HANDLE SENSOR - RH ? X nn	1	\$	255.00	
26	REAR DOOR HANDLE, EXTERIOR - RH ? X nn	1	\$	47.00	
27	REAR DOOR HANDLE MOUNTING BAR - RH ? X nn	1	\$	183.00	
28	REAR DOOR LOCK - RH ? X nn	1	\$	630.00	
29	REAR DOOR HANDLE STRIKER X nn	1	\$	111.00	
30	REAR DOOR HANDLE UNDERLAY STRIKER ? X nn	1	\$	38.00	
31	ROOF MOLDING CHROME - RH - BT	1	\$	706.00	564.80
32	REAR DOOR EDGE PROTECTION - RH ? X nn	1	\$	172.00	
33	REAR DOOR WINDOW - RH X nn	1	\$	322.00	
34	REAR DOOR SEAL, INNER - RH ? X nn	1	\$	657.00	
35	AUDI RING EMBLEM STICKER - AC	1		TBC	58.40
36	SILL PANEL ATTACHMENT PARTS - AC	1	\$	136.00	108.80
37	SILL PANEL ADHESIVE TAPES - AC	1	\$	221.00	176.80
38	REAR WHEEL HOUSING LINER - RH VSB / (RU)	1	\$	299.00	238.80
39	REAR ALUMINIUM RIM - MY	1	\$	1,889.00	1511.20
40	RUBBER VALVE - AC	1	\$	15.00	9.96
SUB TOTAL SPARE PARTS			:	\$ 5,929.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 1306 Z

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	SUSPENSION SUPPORT FRAME ? X nn	1	\$	3,643.00
42	WISHBONE ALUMINIUM - LOWER ? X nn	1	\$	963.00
43	WISHBONE - RH UPPER ? X nn	1	\$	624.00
44	WISHBONE - RH FRONT ? X nn	1	\$	137.00
45	WISHBONE - RH REAR ? X nn	1	\$	501.00
46	TRACK ROD - RH 1 X nn	1	\$	188.00
47	WHEEL BEARING HOUSING - RH ? X nn	1	\$	1,097.00
48	WHEELHUB BEARING ? X nn	1	\$	723.00
49	WHEEL BEARING STONE CHIP GUARD - RH ? X nn	1	\$	49.00
50	GAS SHOCK ABSORBER ? X nn	1	\$	342.00
51	COUPLING ROD ? X nn	1	\$	94.00
52	ANTI-ROLL BAR ? X nn	1	\$	456.00
53	LEVEL SENSOR - RH ? X nn	1	\$	363.00
54	REAR PARKING AID SENSOR - SIDE ? X nn	1	\$	265.00
55	REAR PARKING AID SENSOR SEAL RING 1 6 X nn	6	\$	15.00
56	ARYLIC SEALANT - KC	S/N	\$	180.00 ✓
57	CAVITY WAX - KC	S/N	\$	140.00 ✓
58	STONE CHIP - KC	S/N	\$	180.00 ✓
59	METAL FILLER POWDER - KC	S/N	\$	280.00 ✓
60	1/4 GLASS SEALANT - KC	S/N	\$	100.00 ✓
61	RHS REAR TYRE X nn	S/N	TBC	
62	SUNDRIES ? nec		\$	700.00 89-56 ✓
TOTAL SPARE PARTS		:	\$	34,196.00
TOTAL LABOUR CHARGES		:	\$	27,972.00
GRAND TOTAL		:	\$	62,168.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS :

Steve (LKK)
 23/6/22, 12.37pm

OP-M-M
 EXPIRE - ?
 P/P

My Pul y
 16 ~~hrs~~ dys ✓

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To re-survey the repair work
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal work to be carried out
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W


AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0515/2022/JT 14-Jul-22 CHANG 1 of 1 SLW 1306 Z AUDI A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL FUEL TANK ASSY TO FACILITATE CUTTING OF REAR WHEEL HOUSE PANEL.	S/N \$ 600.00	
GRAND TOTAL		\$ 600.00	

Steve (LKK)

18/7/22

add 3 y)

For Premium Automobiles Pte Ltd



Authorised Signature