

ASS. REC. BY:

REF: CTZ/ 22 006034 1kgv3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. SNM22D204380/C02


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$60k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 09/08 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJT 3065Y Yr Regn: 09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or S.Wagon

Make: Honda Stream c.c. 1799

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____ C/No: RN6 108 2892

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Lanferr

Front R/Bal: 8 mm Rear R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. 21/6/22 D.O.I. 24/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or & M

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Parten Plot</u>
<u>28/06/22 @ 5.30pm</u>	<u>revised to Adeline Chng via Merimen.</u>

Date/Time, File Pass to? : Prell. Report : Final Report

1) _____ Date/Time, File Return to? 2) _____

Days Of Repair: _____ Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Survey Fee:
Transportation:
S - RS. SI
Fines
Others
TOTAL

Report Format : _____ Lump Sum / I.B.I: (\$ _____)



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP CHINA
Policy No:		Date of Loss:	21/06/2022
Vehicle Reg. No.:	SJJ3065Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TOK NGEE CHUANG	Driver (Insured):	TEO HUA YI JONATHAN

Make/Model:	HONDA STREAM, 1.8 X (A)	Vehicle Reg. Date:	08/09/2008
Vehicle Colour:	BLACK		
Engine No:	R18A1792020	Chassis No:	RN61082892
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

*Not Authorized
6/1/2022
Purong Adu Paint*

Description of Accident/Loss	REFER STATEMENT ATTACH
Present Location:	CHENG HOE MOTOR PTE LTD (WOODLANDS)

11 days

COST OF CLAIMS	Amount
Parts	6,502.00
Miscellaneous Items	460.00
Labour	4,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	11,492.00
+ GST 7.00% (\$\$)	804.44
Nett Amount (\$\$)	12,296.44

This claim is handled by: JUNE PHUA LIAN HUA

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	1) TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00 ✓
2	2) TO PANEL BEATING ON REAR PORTION	New	1,800.00 ?
3	3) TO PUTTY AND RESPRAY ON REAR COMPARTMENT, REAR END PANEL, REAR BOTH FENDERS, TAILGATE, REAR BUMPER AND ALL ACCIDENT AFFECTED AREAS	New	1,300.00 1200 ✓
4	4) TO REMOVE AND REFIX REAR EXHAUST AND CHECK LEAKING	New	60.00 ✓
5	5) TO REMOVE AND REFIX REAR GARNISH, SEAT, CUSHION ETC	New	80.00 ✓
6	6) TO REMOVE AND REFIX AIRCON, CHECK AND REFILL GAS	New	100.00 ?
7	7) TO REMOVE AND REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, BONNET; KNOCK AND REPAIR FRT SUPPORT PANEL, FRT FENDER AND RE-ALIGN TO SAME	New	500.00 400 ✓
8	8) TO PUTTY AND RESPRAY ON FRT BUMPER, FRT BUMPER REINFORCEMENT, SUPPORT PANEL, BONNET, FENDERS AND ALL ACCIDENT AFFECTED AREAS	New	700.00 600 ✓
9	9) TO REMOVE AND REFIX CAMERA	New	30.00 ✓
10	10) TO RUSTPROOFING	New	60.00 ✓

Gross Labour Cost (\$\$) 4,530.00

Cheng Hoe Motor Pte Ltd/SJJ3065Y/24/06/2022 13:15. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

1) TO REMOVE WINDSCREEN GLASS
 2) TO PANEL BEATING ON REAR PORTION
 3) TO PUTTY AND RESPRAY ON REAR COMPARTMENT, REAR END PANEL, REAR BOTH FENDERS, TAILGATE, REAR BUMPER AND ALL ACCIDENT AFFECTED AREAS
 4) TO REMOVE AND REFIX REAR EXHAUST AND CHECK LEAKING
 5) TO REMOVE AND REFIX REAR GARNISH, SEAT, CUSHION ETC
 6) TO REMOVE AND REFIX AIRCON, CHECK AND REFILL GAS
 7) TO REMOVE AND REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, BONNET; KNOCK AND REPAIR FRT SUPPORT PANEL, FRT FENDER AND RE-ALIGN TO SAME
 8) TO PUTTY AND RESPRAY ON FRT BUMPER, FRT BUMPER REINFORCEMENT, SUPPORT PANEL, BONNET, FENDERS AND ALL ACCIDENT AFFECTED AREAS
 9) TO REMOVE AND REFIX CAMERA
 10) TO RUSTPROOFING

< END OF ESTIMATES >


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

1) TO REMOVE WINDSCREEN GLASS
 2) TO PANEL BEATING ON REAR PORTION
 3) TO PUTTY AND RESPRAY ON REAR COMPARTMENT, REAR END PANEL, REAR BOTH FENDERS, TAILGATE, REAR BUMPER AND ALL ACCIDENT AFFECTED AREAS
 4) TO REMOVE AND REFIX REAR EXHAUST AND CHECK LEAKING
 5) TO REMOVE AND REFIX REAR GARNISH, SEAT, CUSHION ETC
 6) TO REMOVE AND REFIX AIRCON, CHECK AND REFILL GAS
 7) TO REMOVE AND REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, BONNET; KNOCK AND REPAIR FRT SUPPORT PANEL, FRT FENDER AND RE-ALIGN TO SAME
 8) TO PUTTY AND RESPRAY ON FRT BUMPER, FRT BUMPER REINFORCEMENT, SUPPORT PANEL, BONNET, FENDERS AND ALL ACCIDENT AFFECTED AREAS
 9) TO REMOVE AND REFIX CAMERA
 10) TO RUSTPROOFING

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along North Buona Vista Road towards AYE at the most left lane. All the cars were queuing to Exit the into the Highway and the BMW carplate SBQ 707G hit my car SJJ 3065Y from the back. My car was being pushed forward and hit the back of the mazda 3 SMP 3635K

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 22 Jun 2022
 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 22/6/22
 Reporting Centre Personnel's Signature
 Name: 
 NRIC/FIN No.:

- () Claim Own Policy
- () Claim Third Party
- () Reporting Only
- () Claim OD/TP at other workshop (_____)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/06/2022 15:40 (SGT)
Date of Accident 21/06/2022 17:40 (SGT)
Exact Location of Accident Singapore
Additional Location Information UPP.NORTH BUONA VISTA RD TOWARDS AYE,ALEXANDRA
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJJ3065Y
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner TOK NGEE CHUAN(ZHOU YISHUAN)
NRIC No SXXXX259F
Email Address nicholastok@gmail.com
Mobile Phone No (Phone) +65-90022313
Alternative Phone No +65-90022313

VEHICLE PARTICULARS

Manufacturer Honda
Model STREAM 1.8X A
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1799

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00051812203
Cover Note Number 8/3/22-7/3/23

DRIVER

Name of Driver TOK NGEE CHUAN(ZHOU YISHUAN)
NRIC No SXXXX259F