

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

AUTO 51 LEASING PTE LTD  
 15 YISHUN INDUSTRIAL ST 1 #01-05  
 SINGAPORE 768891

Contact : 67351551 83884444

TPAXA.  
 Xiao Tong.

## TAX INVOICE

Repair Code : CLM17268  
 Date in : 23/06/2022  
 Vehicle Num. : SLT1967G  
 Model : TOYOTA WISH 1.8X CVT  
 Chassis/Eng# : ZGE206033355/2ZR1791245

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>dent</i>	1	698.10	<del>698.10</del> <i>565</i>
REAR BUMPER BRACKET L/R <i>RH dent new</i>	2	55.00	<del>110.00</del> <i>+55</i>
REAR BUMPER END SEAL COVER L/R <i>new</i>	2	87.00	<del>174.00</del> <i>+</i>
REAR BUMPER REFLECTOR L/R <i>cracked</i>	2	59.80	<del>119.60</del> <i>✓</i>
REAR BUMPER SIDE BRACKET L/R <i>cracked</i>	2	46.00	<del>92.00</del> <i>-</i>
REAR BUMPER SIDE RETAINER L/R <i>cracked</i>	2	97.40	<del>194.80</del> <i>-</i>
REAR END LOWER PANEL <i>Repair</i>	1	375.00	<del>375.00</del> <i>+</i>
REAR END PANEL <i>dented</i>	1	540.80	<del>540.80</del> <i>✓</i>
REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	198.00	<del>198.00</del> <i>✓</i>
REAR END PANEL INNER TOP GARNISH <i>dent</i>	1	298.00	<del>298.00</del> <i>-</i>
REAR END PANEL NOSE BRACKET L/R <i>RH dent</i>	2	98.00	<del>196.00</del> <i>98</i>
REAR FENDER INNER TRIM GARNISH L/R <i>new</i>	2	746.50	<del>1,493.00</del> <i>+</i>
REAR SPARE TYRE CARRIAGE BRACKET <i>new</i>	1	328.50	<del>328.50</del> <i>+</i>
REAR TAILGATE <i>dented</i>	1	1477.30	<del>1,477.30</del> <i>1255</i>
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	72.50	<del>72.50</del> <i>+</i>
REAR TAILGATE 'VALVE METIC' EMBLEM <i>new</i>	1	89.10	<del>89.10</del> <i>+</i>
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	33.50	<del>33.50</del> <i>+</i>
REAR TAILGATE INNER TRIM COVER <i>new</i>	1	508.10	<del>508.10</del> <i>+</i>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

AUTO 51 LEASING PTE LTD  
 15 YISHUN INDUSTRIAL ST 1 #01-05  
 SINGAPORE 768891

Contact : 67351551 83884444

**TAX INVOICE**

Repair Code : CLM17268  
 Date in : 23/06/2022  
 Vehicle Num. : SLT1967G  
 Model : TOYOTA WISH 1.8X CVT  
 Chassis/Eng# : ZGE206033355/2ZR1791245

REAR TAILGATE LOCK STRIKER <i>new</i>	1	48.30	<i>x</i>	48.30
REAR TAILGATE MECHANISM LOCK <i>Damage</i>	1	412.70	<i>298</i>	<del>412.70</del>
REAR TAILGATE REFLECTOR L/R <i>new</i>	2	311.80	<i>x</i>	623.60
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	25.10	<i>1</i>	50.20
REAR TAILGATE WEATHER STRIP <i>ct</i>	1	335.70	<i>4890.50</i>	335.70
REAR TAILGATE WINDSCREEN LOWER MOULDING	1	30.90	<i>✓</i>	30.90
REAR TAILGATE WINDSCREEN SIDE MOULDING L/R	2	34.90	<i>3667.87</i>	69.80
REAR TAILGATE WINDSCREEN TOP MOULDING	1	43.10	<i>✓</i>	43.10
REAR TAILLAMP L/R <i>checked</i>	2	375.90	<i>✓</i>	751.80

Subtotal before discount 9,364.40

Percentage discount 25% 2,341.10

**Sub-total 1** 7,023.30

REAR BUMPER CLIPS - SET <i>New</i>	1	50.00	<i>30</i>	<del>50.00</del>
REAR BUMPER END SEAL COVER CLIPS L/R - SET <i>new</i>	2	20.00	<i>1</i>	40.00
REAR BUMPER REVERSE SENSOR - SET <i>Damage</i>	1	250.00	<i>200</i>	<del>250.00</del>
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	20.00	<i>✓</i>	20.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	50.00	<i>x</i>	100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>x</i>	50.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@m51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

AUTO 51 LEASING PTE LTD  
 15 YISHUN INDUSTRIAL ST 1 #01-05  
 SINGAPORE 768891

Contact : 67351551 83884444

**TAX INVOICE**

Repair Code : CLM17268  
 Date in : 23/06/2022  
 Vehicle Num. : SLT1967G  
 Model : TOYOTA WISH 1.8X CVT  
 Chassis/Eng# : ZGE206033355/2ZR1791245

REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00
Subtotal before discount		310	590.00
Percentage discount 0%			0.00
Sub-total 2			590.00
Parts-total			7,613.30

**LABOUR**

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	80.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	80.00
To apply anti-rust chemical on repaired and replaced panel.	60.00
To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.	60.00
<b>Labour Total</b>	<b>2,630.00</b>
<b>Parts &amp; Labour Total</b>	<b>10,243.30</b>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 3

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian  
 H/S 27/06/22  
 OG Pym  
 Total: 5557.87  
 L/S: A7K