



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22006037/Kvy3m4 Date: 05/08/2022 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBT 7979B	Veh. Inspected	SMZ 9439T	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D15522207	Excess (\$)	0.00	
Assign From	KATIE LEE	Assign Date	24/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES GLB200 (A)	c.c	1332	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	W1N2476872W120752	Colour	METALLIC BLUE	
Odometer	23093 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R19	CONTINENTAL	8 mm	
L/H Front Tyre	235/50 R19	CONTINENTAL	8 mm	
R/H Rear Tyre	235/50 R19	CONTINENTAL	8 mm	
L/H Rear Tyre	235/50 R19	CONTINENTAL	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2022	Inspection Date	24/06/2022	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	