

ASS. REC. BY:

REF: U02/ 22 006037/KV

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

05 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

1.151 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMZ 9439TYr Regn: 05, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: MerColour: M. BlueSp. Reading: 23083

Eng/No: \_\_\_\_\_

C/No: WIN 2478872W120752Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD / A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

R/Bal. \_\_\_\_\_

L/Bal. \_\_\_\_\_

D.O.A. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$

Fixes

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

Tech Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SBT7979B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : UNITED OVERSEAS INSURANCE LTD

ACCIDENT DATE : 14/06/2022

TP VEH REG NO : SBT7979B

## ESTIMATE

NO : QUOT202206-000068(00)

DATE : 24/06/2022

POLICY NO : 999995580

VEH REG NO : SMZ9439T

MAKE/MODEL : MERCEDES BENZ GLB200  
AMG LINE

CHASSIS NO : W1N2476872W120752

ENGINE NO : 28291480552982

REG. DATE : 2021

## Estimate Repair Cost to Vehicle No : SMZ9439T

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>NET PRICE</b>			
1 Rear sport rim - RH	1	1,580.00	1,580.00
2 Rear wheel arch garnish -- RH	1	190.00	190.00
3 Rear door - RH	1	3,005.00	3,005.00
4 Rear door weatherstrip - RH	1	328.00	328.00
5 Rear door seal (front) -- RH	1	68.00	68.00
6 Rear door trimboard rivets - RH	20	12.00	240.00
7 Rear door protector clips -- RH	12	9.00	108.00
8 Front door - RH	1	2,075.00	2,075.00
9 Front door weatherstrip - RH	1	328.00	328.00
10 Front door trimboard rivets - RH	20	12.00	240.00
11 Front door protector clips - RH	10	9.00	90.00
			8,252.00
		Less 10%	825.20
			7,426.80
<b>LABOUR</b>			
12 To transfer RH front & rear door interior mechanism & glass to new door	1	300.00	300.00
13 To check and rectify wiring system	1	80.00	80.00
14 To panel beat and straighten RH rear wheel arch panel, RH rear chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
15 To putty and spray paint on affected areas	1	1,200.00	1,200.00
16 To apply rust proofing on repaired and repalced panels	1	160.00	160.00
17 To computerise check wheel alignment	1	120.00	120.00
			2,860.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary work to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL S\$ 10,286.80

ADD GST @ 7% 720.08

GRAND TOTAL S\$ 11,006.88

SINGAPORE DOLLAR ELEVEN THOUSAND SIX AND CENTS EIGHTY-EIGHT ONLY



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	15/06/2022 23:08 (SGT)
Date of Accident	14/06/2022 19:05 (SGT)
Exact Location of Accident	New Bridge Rd, New Bridge Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMZ9439T

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Company Reg No	1XXXXX778Z
Email Address	mohamed_faizal.mohd_yasin@mercedes-benz.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

#### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Glb 200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	


#### DRIVER

Name of Driver	NG YAO HWEE
NRIC No	SXXXX243E



# ACCIDENT DIAGRAM

Ver. 30042021



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**VERIFIED BY AJAX MARS (ARC)**  
**REPORTING OFFICER**  
MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: