



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2206843
INV Date 04/11/2022
Reference CC4/LPC22006040/Kpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SNC 8928P
Insured Veh. GBC 197B
Claim No. 22/22/22/VC05/025966
Policy No. Z22VC05009429
Accident Date 22/06/2022
Inspection Date 27/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC22006040/Kpa3q2

Date: 04/11/2022

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 197B	Veh. Inspected	SNC 8928P
Policy No.	Z22VC05009429	Coverage (\$)	0.00
Claim No.	22/22/22/VC05/025966	Excess (\$)	0.00
Assign From	GERALD	Assign Date	24/06/2022

2. Vehicle Particulars & Condition

Make & Model	TESLA MODEL 3 (A)	c.c	0
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	LRW3F7FA9MC384625	Colour	METALLIC PEARL WHITE
Odometer	10589 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45Z R18	MICHELIN	9 mm
L/H Front Tyre	235/45Z R18	MICHELIN	9 mm
R/H Rear Tyre	235/45Z R18	MICHELIN	9 mm
L/H Rear Tyre	235/45Z R18	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/06/2022	Inspection Date	27/06/2022
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 8928P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	BENT	728.97	728.97
1	REAR BOOTLID "TESLA" EMBLEM	NECESSARY	37.38	37.38
1	REAR BOOTLID LAMP LH	SERVICEABLE	177.57	-
1	REAR BOOTLID LAMP RH	SERVICEABLE	177.57	-
1	REAR BOOTLID MECHANISM LOCK	TO REPAIR SEE LABOUR	54.21	-
1	REAR BOOTLID INNER TRIM BOARD	SERVICEABLE	345.79	-
1	REAR BOOTLID HINGE LH	SERVICEABLE	61.68	-
1	REAR BOOTLID HINGE RH	SERVICEABLE	61.68	-
1	REAR BOOTLID WEATHERSTRIP	NECESSARY	121.50	121.50
1	REAR TAILLAMP LH	SERVICEABLE	280.37	-
1	REAR TAIL LAMP RH	SERVICEABLE	280.37	-
1	REAR TAIL LAMP BRACKET LH	SERVICEABLE	2.80	-
1	REAR TAIL LAMP BRACKET RH	SERVICEABLE	2.80	-
1	REAR BUMPER	BUCKLED	663.55	663.55
1	REAR BUMPER SIDE BRACKET LH	CRACKED	7.48	7.48
1	REAR BUMPER SIDE BRACKET RH	CRACKED	7.48	7.48
1	REAR BUMPER CENTER BRACKET	CRACKED	52.34	52.34
1	REAR BUMPER LOWER LIP	DEFORMED	140.19	140.19
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	20.56	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	20.56	-
2	REAR BUMPER PARKING SENSOR @\$158.88	SHORTED (1PC ONLY)	317.76	158.88
2	REAR BUMPER PARKING SENSOR BRACKET @\$4.67	NECESSARY (1PC ONLY)	9.34	4.67
1	REAR BUMPER REINFORCEMENT	DEFORMED	271.03	271.03
1	REAR END PANEL TOP GARNISH	SERVICEABLE	299.07	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-414.21	-219.35
			3,727.84	1,974.12

Report Ref No. CC4/LPC22006040/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	REAR BOOTLID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	DENTED	50.00	45.00
			160.00	105.00
LABOUR				
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID MECHANISM LOCK AND REAR END PANEL.		800.00	400.00
	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.		800.00	440.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR.		120.00	60.00
	TO REMOVE & REINSTALL REAR BOOTLID MECHANISM BACK TO ORIGINAL FUNCTIONS.		100.00	60.00
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.	NOT NECESSARY	150.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		120.00	15.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.	NOT NECESSARY	100.00	-
			2,190.00	975.00
GRAND TOTAL			6,077.84	3,054.12
RECOMMENDED COST OF REPAIRS				3,054.12

Report Ref No. CC4/LPC22006040/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNC 8928P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNC 8928P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNC 8928P

RE-INSPECTION

