

Date: 24/06/2022

Vehicle No: SNC8928P

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA9MC384625

Reg.Year: 2021

*NOT Authorized
Repair By party
4 days*

Third Party Insurer: LONPAC

Third Party Veh No: GBC197B

Date of Accident: 22/06/2022

Estimator: KIT

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BOOTLID	1		<i>Bu</i> \$728.97	✓
2	REAR BOOTLID "TESLA" EMBLEM	1		<i>ma</i> \$37.38	✓
3	REAR BOOTLID LAMP LH	1		<i>pu</i> \$177.57	X
4	REAR BOOTLID LAMP RH	1		<i>pu</i> \$177.57	X
5	REAR BOOTLID MECHANISM LOCK	1		<i>R</i> \$54.21	X
6	REAR BOOTLID INNER TRIM BOARD	1		<i>pu</i> \$345.79	X
7	REAR BOOTLID HINGE LH	1		\$61.68	?
8	REAR BOOTLID HINGE RH	1		\$61.68	?
9	REAR BOOTLID WEATHERSTRIP	1		\$121.50	?
10	REAR TAIL LAMP LH	1		<i>pu</i> \$280.37	X
11	REAR TAIL LAMP RH	1		<i>pu</i> \$280.37	X
12	REAR TAIL LAMP BRACKET LH	1		<i>pu</i> \$2.80	X
13	REAR TAIL LAMP BRACKET RH	1		<i>pu</i> \$2.80	X
14	REAR BUMPER	1		<i>Bu</i> \$663.55	✓
15	REAR BUMPER SIDE BRACKET LH	1		<i>pu</i> \$7.48	X
16	REAR BUMPER SIDE BRACKET RH	1		<i>pu</i> \$7.48	X
17	REAR BUMPER CENTER BRACKET	1		\$52.34	?
18	REAR BUMPER LOWER LIP	1		<i>pu</i> \$140.19	X
19	REAR BUMPER REFLECTOR LH	1		<i>pu</i> \$20.56	X
20	REAR BUMPER REFLECTOR RH	1		<i>pu</i> \$20.56	X
21	REAR BUMPER PARKING SENSOR	2	\$158.88	\$317.76	?
22	REAR BUMPER PARKING SENSOR BRACKET	2	\$4.67	\$9.34	?
23	REAR BUMPER REINFORCEMENT	1		\$271.03	?
24	REAR END PANEL TOP GARNISH	1		<i>pu</i> \$299.07	X
25	REAR END PANEL	1		REPAIR	
				SUB TOTAL	\$4,142.05
				LESS 10%	\$414.21
				PARTS TOTAL	\$3,727.85

Date: 24/06/2022
 Vehicle No: SNC8928P
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA9MC384625
 Reg.Year: 2021

Third Party Insurer: LONPAC
 Third Party Veh No: GBC197B
 Date of Accident: 22/06/2022
 Estimator: KIT
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID INNER TRIM BOARD CLIPS	1		<i>nn</i> \$50.00
2	REAR BUMPER CLIPS	1		<i>nn</i> \$60.00
3	REAR NUMBER PLATE WITH HOLDER	1		<i>nn</i> \$50.00
S/N TOTAL				\$160.00

X
✓
450

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$800.00 *400*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$800.00 *400*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR. \$120.00 *60*

TO REMOVE & REINSTALL REAR BOOTLID MECHANISM BACK TO ORIGINAL FUNCTIONS. \$100.00 *60*

TO DAIGNOSIS FAULT CODE & RESET MEMORY. \$150.00 *7*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$120.00 *15*

TO TUFF KOTE & UNDERSEAL MATERIALS. *nn* \$100.00 *X*

LABOUR TOTAL \$2,190.00

KIT TOTAL \$6,077.85