

Date: 24/06/2022
 Vehicle No: SNC8928P
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA9MC384625
 Reg.Year: 2021

*NOT Authorized
 Recovery Bk party
 4 days*

Third Party Insurer: LONPAC
 Third Party Veh No: GBC197B
 Date of Accident: 22/06/2022
 Estimator: KIT
 Surveyor:

ESTIMATE

| NO. | DESCRIPTION | QTY | UNIT S\$ | AMOUNT S\$ | | |
|-----|------------------------------------|---------|----------|--------------------|------------|------|
| 1 | REAR BOOTLID | 1 | | <i>Bu</i> \$728.97 | ✓ | |
| 2 | REAR BOOTLID "TESLA" EMBLEM | 1 | | <i>ma</i> \$37.38 | ✓ | |
| 3 | REAR BOOTLID LAMP LH | 1 | | <i>pu</i> \$177.57 | X | |
| 4 | REAR BOOTLID LAMP RH | 1 | | <i>pu</i> \$177.57 | X | |
| 5 | REAR BOOTLID MECHANISM LOCK | 1 | | <i>R</i> \$54.21 | X | |
| 6 | REAR BOOTLID INNER TRIM BOARD | 1 | | <i>pu</i> \$345.79 | X | |
| 7 | REAR BOOTLID HINGE LH | 1 | | svc \$61.68 | X | |
| 8 | REAR BOOTLID HINGE RH | 1 | | svc \$61.68 | X | |
| 9 | REAR BOOTLID WEATHERSTRIP | 1 | | Nec \$121.50 | ✓ | |
| 10 | REAR TAIL LAMP LH | 1 | | <i>pu</i> \$280.37 | X | |
| 11 | REAR TAIL LAMP RH | 1 | | <i>pu</i> \$280.37 | X | |
| 12 | REAR TAIL LAMP BRACKET LH | 1 | | <i>pu</i> \$2.80 | X | |
| 13 | REAR TAIL LAMP BRACKET RH | 1 | | <i>pu</i> \$2.80 | X | |
| 14 | REAR BUMPER | 1 | | <i>Bu</i> \$663.55 | ✓ | |
| 15 | REAR BUMPER SIDE BRACKET LH | 1 | cra | <i>pu</i> \$7.48 | X | |
| 16 | REAR BUMPER SIDE BRACKET RH | 1 | cra | <i>pu</i> \$7.48 | X | |
| 17 | REAR BUMPER CENTER BRACKET | 1 | cra | \$52.34 | ✓ | |
| 18 | REAR BUMPER LOWER LIP | 1 | Def | <i>pu</i> \$140.19 | X | |
| 19 | REAR BUMPER REFLECTOR LH | 1 | | <i>pu</i> \$20.56 | X | |
| 20 | REAR BUMPER REFLECTOR RH | 1 | | <i>pu</i> \$20.56 | X | |
| 21 | REAR BUMPER PARKING SENSOR | Shorted | 2 | \$158.88 | \$317.76 | 71pc |
| 22 | REAR BUMPER PARKING SENSOR BRACKET | Nec | 2 | \$4.67 | \$9.34 | ✓ |
| 23 | REAR BUMPER REINFORCEMENT | 1 | | Def | \$271.03 | ✓ |
| 24 | REAR END PANEL TOP GARNISH | 1 | | <i>pu</i> \$299.07 | X | |
| 25 | REAR END PANEL | 1 | | R REPAIR | X | |
| | | | | SUB TOTAL | \$4,142.05 | |
| | | | | LESS 10% | \$414.21 | |
| | | | | PARTS TOTAL | \$3,727.85 | |

Date: 24/06/2022
 Vehicle No: SNC8928P
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA9MC384625
 Reg.Year: 2021

Third Party Insurer: LONPAC
 Third Party Veh No: GBC197B
 Date of Accident: 22/06/2022
 Estimator: KIT
 Surveyor:

| NO. | SPECIAL NETT | QTY | UNIT S\$ | AMOUNT S\$ |
|-----------|-------------------------------------|-----|----------|-------------------|
| 1 | REAR BOOTLID INNER TRIM BOARD CLIPS | 1 | | <i>nn</i> \$50.00 |
| 2 | REAR BUMPER CLIPS | 1 | | <i>nn</i> \$60.00 |
| 3 | REAR NUMBER PLATE WITH HOLDER | 1 | | <i>nn</i> \$50.00 |
| S/N TOTAL | | | | \$160.00 |

X
✓
4500

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$800.00 *4000*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$800.00 *4400*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR. \$120.00 *600*

TO REMOVE & REINSTALL REAR BOOTLID MECHANISM BACK TO ORIGINAL FUNCTIONS. \$100.00 *600*

TO DAIGNOSIS FAULT CODE & RESET MEMORY. NN \$150.00 *7X*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$120.00 *150*

TO TUFF KOTE & UNDERSEAL MATERIALS. *nn* \$100.00 *X*

LABOUR TOTAL \$2,190.00

TOTAL \$6,077.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

