

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006042/UQY3M4**Date:** 13/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00015202101		
<b>Claimant Vehicle No :</b>	SLW2026A	<b>Insured Vehicle No :</b>	SMV1263G		
Date of Loss:	18/06/2022	Nature of Claim:	TP	Claim No:	SNM22D204341/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLW2026A		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK048693
Reg. Date:	31/01/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF42JA058258
Colour:	Grey	Odometer:	60912 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,253.16	2,731.27	5,521.89	66.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	770.00	1,160.00	60.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,183.16</b>	<b>3,501.27</b>	<b>6,681.89</b>	<b>65.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>(S\$)</b>	10,183.16	2,800.00	7,383.16	72.50
<b>+ GST 7.00/7.00% (S\$)</b>	712.82	196.00	516.82	72.50
<b>Nett Amount (S\$)</b>	<b>10,895.98</b>	<b>2,996.00</b>	<b>7,899.98</b>	<b>72.50</b>

**INSPECTION**

Date of Assignment:	24/06/2022		
Date Inspected:	04/07/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 13 Jul 2022)

**Parts:** 143      AUDI A4 2.0 SEDAN TFSI S-TRONIC (NAV) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLW2026A)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,065.77 FL	*1,918.00 FL
2	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	45.00 FL	*- FL
4	1		*REAR BUMPER SENSOR (ORIGINAL) @\$257.50 (4pcs)	Shorted (1Piece Only)	1,030.00 FL	*205.00 FL
5	4		*REAR BUMPER SENSOR HOLDER @\$65.00	Not Necessary	260.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	567.75 FL	*567.75 FL
7	1		*REAR BUMPER SPONGE	No Such Parts	238.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER @\$65.40	Not Necessary	130.80 FL	*- FL
9	2		*REAR BUMPER REFLECTOR LAMP @\$85.00	Not Necessary	170.00 FL	*- FL
10	1		*REAR BOOT	Not Necessary	2,406.35 FL	*- FL
11	1		*REAR BOOT A4 WORDING	Not Necessary	84.23 FL	*- FL
12	1		*REAR BOOT TFSI WORDING	Not Necessary	93.23 FL	*- FL
13	1		*REAR END PANEL	Repair	1,518.97 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	160.52 FL	*- FL
15	1		*REAR BUMPER LOWER	Grazed	294.00 FL	*294.00 FL
16	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,164.62</b>	<b>3,034.75</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	911.46	303.48
<b>Total Parts (\$\$)</b>	<b>8,253.16</b>	<b>2,731.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	400.00
2	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	800.00	300.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	100.00	50.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>1,930.00</b>	<b>770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >