

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Singapore Civil Defence Force
91 Ubi Avenue 4
Singapore 408827

Claim Details

Case Ref. No. : TP/062022/5496
Date : 27-06-2022
Accident Date : 13-06-2022

Vehicle Details

Make & Model : Volkswagen SPORTSVAN 1.4
HIGHLINE AM14HZ
Chassis No : WVVZZZAUZGW599098
Registration No : SY40C

Third Party Vehicle Details

Registration No : GBF8696J

S/N	Description	Qty	Amount (\$)
1	FRONT BUMPER repair	1.00	\$890.00
2	FRONT BUMPER PARKING SENSOR 2, new	1.00	\$165.00
3	FRONT BUMPER SPONGE X 2	1.00	\$69.00
4	FRONT BUMPER REINFORCEMENT X 2	1.00	\$520.00
5	FRONT BUMPER CLIPS X 2	10.00	\$700.00
6	FRONT GRILLE ASSY cm	1.00	\$470.00
			571.50
			400.00
			971.50
			635
			10%
			571.50
			\$2,814.00
			(Discount: -10%)
			(\$281.40)
			\$2,532.60

7 TO REPAIR DAMAGES
8 TO SPRAY PAINTING

Subtotal w/o GST:

\$3,492.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

Rand
Hp 90010068
2 days
P/P
27/06/22 @ 15:45
Reg after paint
new grille photo