



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SLM2683E

Date of Accident : 23 May 2022

Mr Abdul Rashid Bin Sapuan

Date : 30 June 2022

Not Allowed
Lm
24/06/22
1/5 & 4200
5 days.

Estimate To Repair SKB1952E - Toyota COROLLAALTIS 1.6 AUTO

Chassis No : MR053REE104116671

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper <i>reflector Dis</i>	\$ 588.10
02	2 pcs	rear bumper reflector @ \$95.00 <i>un</i>	\$ 190.00
03	2 pcs	rear bumper rod with absorber @ \$166.80 <i>Torn</i>	\$ 333.60
04	2 pcs	rear bumper bracket @ \$87.10 <i>un</i>	\$ 174.20
05	2 pcs	rear bumper side retractor @ \$69.80 <i>un</i>	\$ 139.60
06	3 pcs	rear bumper holder @ \$77.00 <i>un</i>	\$ 231.00
07	1 pc	rear end panel <i>Bed 6100</i>	\$ 580.60
08	1 pc	rear end panel inner trim <i>un</i>	\$ 202.70
09	2 pcs	rear end panel inner trim clip @ \$4.30 <i>un</i>	\$ 8.60
10	2 pcs	rear tail lamp @ \$346.10 <i>CNE</i>	\$ 692.20
11	2 pcs	rear tail lamp clip holder @ \$7.10 <i>un</i>	\$ 14.20
12	1 pc	bootlid <i>un / 34C</i>	\$ 899.00
13	1 pc	bootlid chrome moulding <i>un</i>	\$ 220.00
14	1 pc	bootlid insulator <i>un</i>	\$ 250.00
15	9 pcs	bootlid insulator clip @ \$3.90 <i>un</i>	\$ 35.10
16	2 pcs	bootlid lamp @ \$220.00 <i>un</i>	\$ 440.00
17	1 pc	bootlid lock <i>un</i>	\$ 210.00
18	1 pc	bootlid catch <i>un</i>	\$ 65.00
19	1 pc	rear spare tyer panel board <i>Torn</i>	\$ 267.00
20	1 pc	bootlid weatherstrip <i>un</i>	\$ 166.80
			\$ 5,707.70
Less 25 %			\$ 1,426.93
			\$ 4,280.77
<u>SPECIAL NETT ITEMS</u>			
21	1 pc	rear number plate <i>un</i>	\$ 50.00
22	1 set	rear bumper sensor <i>sketch</i>	\$ 300.00
23	1 pc	rear camera <i>un</i>	\$ 550.00
			\$ 900.00
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 120.00
02		To reinstall of rear bumper parking sensor.	\$ 80.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
04		To check electrical lighting concerned.	\$ 60.00
05		To rust-proofing of the affected areas.	\$ 200.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLM2683E

Date of Accident : 23 May 2022

Mr Abdul Rashid Bin Sapuan

Date : 30 June 2022

Estimate To Repair SKB1952E - Toyota COROLLA ALTIS 1.6 AUTO

Chassis No : MR053REE104116671

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u>	
		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,510.00
		Total	\$ 7,690.78

900

P- 4087
25%

P- 3065.25

S- N 200

A- 1900

5255.25

20%

4204

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: