



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22005037/Eqy3m4-1 Date: 29/06/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBA 5219A	Veh. Inspected	SKT 3771C	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025851	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	23/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053REH104533575	Colour	BLUE	
Odometer	141788 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	4 mm	
L/H Front Tyre	205/55 R16	DUNLOP	4 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	4 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/05/2022	Inspection Date	01/06/2022	
Survey held at	TRINICE AUTOMOBILE SERVICES BLK 1001 BUKIT MERAH LANE 3 #01-63 SINGAPORE 159724			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	