



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 394C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER LH	TO REPAIR SEE LABOUR	992.04	-
1	REAR BUMPER SIDE BRACKET RH	NOT NECESSARY	94.80	-
	LESS 25% DISCOUNT		-271.71	-
			815.13	-
SPECIAL NETT ITEMS				
1	PETROL STICKER (SN)	NECESSARY	25.00	25.00
			25.00	25.00
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		950.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/ REFIX UPHOLSTERY.	NOT NECESSARY	90.00	-
	CHECK WIRING.	NOT NECESSARY	60.00	-
			1,700.00	850.00
GRAND TOTAL			2,540.13	875.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				875.00

Report Ref No. NS/INC22006058/Tcm4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.