

REPAIR ESTIMATE\*

VEHICLE NO SH 6033Z  
MAKE REG 09.062016  
MODEL I-40

DATE 06.06.2022  
MVA CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR PANEL RH			<del>KY</del> \$2,707.70
1	FRONT DOOR WING MIRROR RH			<del>RY</del> \$760.00
1	FRONT WHEEL COVER RH			<del>ny</del> X \$217.20
1	REAR WHEEL COVER RH			<del>ny</del> X \$217.20
1	REAR DOOR PANEL RH			<del>ht</del> \$2,201.10
	<b>SUB TOTAL</b>		2201.10	<b>\$6,103.20</b>
	<b>20.00%</b>		1760.88	<b>\$1,220.64</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$4,882.56</b>
1	REAR FENDER ADVERTISEMENT			<del>rec</del> \$100.00
1	REAR DOOR ADVERTISEMENT			<del>int</del> \$100.00
1	FRONT DDOR ADVERTISEMENT			<del>int</del> \$100.00
1	FRONT DOOR COMFORT STICKER			<del>we</del> \$75.00
1	REAR DOOR COMFORT APP STICKER		455	<del>we</del> \$80.00
				<del>\$438.50</del>
	<b>Labour Charge</b>			\$455.00
	Panel Beating		1370	<del>560</del> \$600.00
	Spray Painting Charge			<del>750</del> \$800.00
	Remove/Refix door part front & rear.			<del>80</del> \$180.00
	<b>TOTAL LABOUR</b>		3585	<b>\$1,580.00</b>
	<b>ESTIMATE TOTAL</b>		4154 2850	<del>\$6,991.06</del>
			30 days	\$6,917.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphn 97475740  
wp 7/6/22 2540  
c/s Resury after repair  
Tanphn 8 16 hours  
2-3 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: