

REPAIR ESTIMATE*

VEHICLE NO SH 6033Z
MAKE REG 09.062016
MODEL I-40

DATE 06.06.2022
MVA CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR PANEL RH			KY \$2,707.70
1	FRONT DOOR WING MIRROR RH			RY \$760.00
1	FRONT WHEEL COVER RH			ny X \$217.20
1	REAR WHEEL COVER RH			ny X \$217.20
1	REAR DOOR PANEL RH			ht \$2,201.10
	SUB TOTAL		2201.10	\$6,103.20
	20.00%		1760.88	\$1,220.64
	DISCOUNTED TOTAL			\$4,882.56
1	REAR FENDER ADVERTISEMENT			rec \$100.00
1	REAR DOOR ADVERTISEMENT			int \$100.00
1	FRONT DDOR ADVERTISEMENT			int \$100.00
1	FRONT DOOR COMFORT STICKER			we \$75.00
1	REAR DOOR COMFORT APP STICKER		455	we \$80.00
				\$438.50
	Labour Charge			
	Panel Beating		1370	560 \$600.00
	Spray Painting Charge			750 \$800.00
	Remove/Refix door part front & rear.			80 \$180.00
	TOTAL LABOUR		3585	\$1,580.00
	ESTIMATE TOTAL		4154 2850 30 days	\$6,901.06
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphn 97475740
wp 7/6/22 2850
c/s Resurvey after repair
Tanphn & 16 hours
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: