

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6033Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR PANEL RH	TO REPAIR SEE LABOUR	2,707.70	-
1	FRONT DOOR WING MIRROR RH	TO REPAIR SEE LABOUR	760.00	-
1	FRONT WHEEL COVER RH	NOT NECESSARY	217.20	-
1	REAR WHEEL COVER RH	NOT NECESSARY	217.20	-
1	REAR DOOR PANEL RH	BENT	2,201.10	2,201.10
	LESS 20% DISCOUNT		-1,220.64	-440.22
			4,882.56	1,760.88
	<u>SPECIAL NETT ITEMS</u>			
1	REAR FENDER ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT (SN)	CUT	100.00	100.00
1	FRONT DOOR ADVERTISEMENT (SN)	CUT	100.00	100.00
1	FRONT DOOR COMFORT STICKER (SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT APP STICKER (SN)	NECESSARY	80.00	80.00
			455.00	455.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT DOOR PANEL RH AND FRONT DOOR WING MIRROR RH.		600.00	560.00
	SPRAY PAINTING CHARGE.		800.00	750.00
	REMOVE / REFIX DOOR PART FRONT & REAR.		180.00	60.00
			1,580.00	1,370.00
GRAND TOTAL			6,917.56	3,585.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,850.00

Report Ref No. NS/INC22006059/Tce2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.