

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 526P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER BEAM	CRACKED	394.80	394.80
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	FOG LAMP	NOT NECESSARY	201.50	-
1	ANTENNA ASSY-SMARTKEY	NOT NECESSARY	40.50	-
1	REAR BUMPER BEAM STAY LH	NOT NECESSARY	138.10	-
1	REAR BUMPER BEAM STAY RH	NOT NECESSARY	138.10	-
1	REAR BUMPER TOW COVER	DEFORMED	98.80	98.80
	LESS 20% DISCOUNT		-388.89	-285.25
			1,555.56	1,141.00
	NETT ITEMS			
1	REAR NUMBER PLATE (N)	CRACKED	50.00	50.00
1	REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-	-23.00
			230.00	207.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	ADVERTISEMENT LOGO - FENDER (SN)	NECESSARY	200.00	200.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINT.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		50.00	30.00
	CHECK WIRING.	NOT NECESSARY	50.00	_
			800.00	630.00
	GRAND TOTAL		2,835.56	2,228.00

Report Ref No. NS/INC22006061/Tqce2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,800.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC22006061/Tqce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.