

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC 526P

DATE: 13.06.22

MAKE HYUNDAI

MVA JUMANI

MODEL IONIQ

DOA: 12.06.22

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER ASSY			\$459.40	
1	REAR BUMPER CENTRE MOULDING			\$451.25	
1	REAR BUMPER BEAM			\$394.80	
10	REAR BUMPER CLIPS			\$22.00	
1	FOG LAMP			\$201.50	
1	ANTENNA ASSY – SMARTKEY			\$40.50	
1	REAR BUMPER BEAM STAY LH			\$138.10	
1	REAR BUMPER BEAM STAY RH			\$138.10	
1	REAR BUMPER TOW COVER			\$98.80	
1					
	SUB TOTAL			\$1,944.45	
	LESS 20%			\$388.89	
	DISCOUNTED TOTAL			\$1,555.56	
	REAR NUMBER PLATE			\$50.00	NET
	REVERSE SENSOR			\$180.00	NET
	REAR BUMPER MAT			\$50.00	NET
					NET
				\$280.00	
	Labour Charge				
	PANEL BEATING			\$400.00	
	SPRAY PAINT			\$300.00	
	REMOVE / REFIX REVERSE SENSOR			\$50.00	
	CHECK WIRING			\$50.00	
	ADVERTISEMENT LOGO - FENDER			\$200.00	
	<i>Taufik 97495749</i>				
	<i>wp 1030 14/6/20</i>				
	<i>02 days</i>				
	<i>1/5 hours after up</i>				
	<i>Lapni Chhaban</i>				
	TOTAL LABOUR			\$1,000.00	
	ESTIMATE TOTAL			\$2,835.56	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 13.06.2022 13:37

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4276557

JC NO.305519415

OWNER

AS CITYCAB PTE LTD

OWNER NO. 7010070

RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65551188

(O)

(P)

OUNT CARD NO.

REGN NO.:

SHC 526P

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

12.06.2022 15:40

DATE/TIME IN

YR OF MANU.

30.04.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU141343

COMPLETION DATE/TIME:

JOB DESCRIPTION


ccident Date: 12.06.2022

ATURE: 3P 12.06.2022

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

No.: SHC 526P

JU NTUC

Vehicle No.:

SHC 526P

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard