

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH8710P

Make : HYUNDAI

Model : IONIQ(G3)

Date: 15.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH RH		138.1	\$276.20
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR BUMPER LICENCE LAMP			\$85.30
1	ANTENNA ASSY SMARTKEY			\$40.50
2	REAR BUMPER SIDE BRACKET LH RH			\$111.60
1	BOOTLID			\$2,549.70
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	REAR BUMPER TOWING COVER			\$98.80
1	REAR PANEL			\$532.00
1	REAR PANEL GARNISH			\$246.80
	<b>SUB TOTAL</b>		4012.85	\$5,549.75
	<b>LESS 20%</b>		3210.28	\$1,109.95
	<b>DISCOUNTED TOTAL</b>			<b>\$4,439.80</b>
	REAR FENDER ADVERTISEMENT STICKER LH		SN 300	\$100.00
	REAR FENDER ADVERTISEMENT STICKER RH			\$100.00
	BOOTLID ADVERTISEMENT STICKER			\$100.00
	REAR NUMBER PLATE WITH TRIM COVER			\$55.00
	BOOTLID COMFORT TEL NO STICKER			\$40.00
	BOOTLID COMFORT LOGO STICKER			\$30.00
	BOOTLID COMFORT APP STICKER			\$30.00
	REAR BUMPER REVERSE SENSOR			\$180.00
				<b>\$435.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$1,100.00
	SPRAY PAINTING CHARGE			\$600.00
	CHK ALL LIGHTING			\$60.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	<b>TOTAL LABOUR</b>			<b>\$1,900.00</b>
	<b>ESTIMATE TOTAL</b>		5136.78	<b>\$6,774.80</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12/6/20

Tanpin 97495749  
 up 15/6/22 @ 415m  
 LK Resurvey after repair  
 Tanpin @ 1/1/2020

ESTIMATE TOTAL

3 days

6593900  
 30 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.