

ASS. REC. BY: Taufik

REF:

INC NS/INC22006064/Tqc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	<u>✓</u>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WN'

Date: _____ Person Contacted: Aring Vehicle: IN / OUT

Veh No: SH 6285M Yr Regn: 2019, oct
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Wing c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 404119 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCR851CVLH186052

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: NI / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/65R15

R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or wentlake

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP-INC-SKM9851C.</u>
	<u>Taufikh finalised LS \$1150, 2 days (Red \$2390.68, 68%)</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Date/Time, File Return to? _____

Report Format: TP
Lump Sum / H.E. / 1150

Days Of Repair: 2
Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS:	SI
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH6285M

15.06.2022

MAKE REG 22.10.2019

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		100 \$459.40
2	REAR BUMPER SIDE BRACKET LH/RH		X \$111.60
1	REAR BUMPER REINFORCEMENT		? \$394.80
2	REAR BUMPER REINFORCEMENT STAY LH/RH		? \$276.20
1	REAR BUMPER CENTRE MOULDING		de \$451.25
1	REAR BUMPER CENTRE LOWER MOULDING		? \$155.00
1	TOW COVER		X \$98.80
2	NUMBER PLATE LAMP LH/RH		\$85.30 X \$170.60
1	REAR FOG LAMP		? \$210.50
1	REAR SMART ANTENNA		? \$40.50
1	REAR BUMPER REFLECTOR RH		X \$41.45
10	REAR BUMPER CLIPS		\$2.20 100 \$22.00
SUB TOTAL			\$2,432.10
20.00%			\$486.42
DISCOUNTED TOTAL			\$1,945.68
1	BOOTLID ADVERTISEMENT		X \$100.00
2	REAR FENDER ADVERTISEMENT		mer \$200.00
1	REAR NUMBER PLATE W/HOLDER		ana \$55.00
1	REAR REVERSE SENSOR		mer \$180.00
Labour Charge			\$515.00
	Panel Beating		250 \$600.00
	Spray Painting Charge		250 \$300.00
	Check Lighting and Wiring		X \$60.00
	Tuff Coating		X \$60.00
	Remove/refix Reverse sensor		30 X \$60.00
TOTAL LABOUR			\$1,080.00
ESTIMATE TOTAL			\$3,540.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfim 97495749
wp 15/6/22 @ 480 p.
L/S Resurvey after repair
Tanfimi @ lkhark.com
02 days

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4290800


JC NO305519824

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 TEL (R) 65508755 (O) (P) ACCOUNT CARD NO.	REGN NO.: SH 6285M	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 15.06.2022 10:50
	YR OF MANU. 22.10.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLUJ186052	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 15.06.2022
NATURE: 3P 15.06.2022

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY: _____

_____ SERVICE ADVISOR	_____ CUSTOMER'S SIGNATURE
--------------------------	-------------------------------

Acknowledgement Slip
 No.: **SH 6285M** **CHIANG**

 Signature/Date

Exit Pass
 Vehicle No.: **SH 6285M**

 Name of Service Advisor _____
 Date
 To be kept by Security Guard

Returned to Service Reception upon collection