



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 3443S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (N) (CONSISTENT)	BUCKLED / CUT	1,230.00	1,230.00
1	REAR BUMPER SIDE RETAINER -RH (N) (CONSISTENT)	DISTORTED	38.00	38.00
1	REAR BUMPER SENSOR (N) (CONSISTENT)	* CHECK	215.00	-
8	REAR BUMPER SENSOR SEALS @\$12.00 (N) (CONSISTENT)	* CHECK	96.00	-
15	REAR BUMPER CLIPS @\$9.00 (N) (CONSISTENT)	NECESSARY	135.00	135.00
1	REAR FENDER -RH (N) (CONSISTENT)	BENT	2,680.00	2,680.00
1	REAR SPORT RIM -RH (N) (CONSISTENT)	DENTED	950.00	950.00
1	REAR WHEEL ARCH GARNISH -RH (N) (CONSISTENT)	DISTORTED / CUT	260.00	260.00
1	TAILLAMP ASSY -RH (N) (CONSISTENT)	SERVICEABLE	848.00	-
1	TAILLAMP LOWER BRACKET -RH (N) (CONSISTENT)	* CHECK	73.00	-
1	REAR DOOR -RH (N) (CONSISTENT)	BENT	2,205.00	2,205.00
1	REAR DOOR WEATHERSTRIP -RH (N) (CONSISTENT)	NECESSARY	328.00	328.00
20	REAR DOOR TRIMBOARD RIVETS-RH @\$12.00 (N) (CONSISTENT)	* CHECK	240.00	-
1	REAR DOOR STICKER -RH (N) (CONSISTENT)	NECESSARY	98.00	98.00
	LESS 10% DISCOUNT		-939.60	-792.40
			8,456.40	7,131.60
<u>LABOUR</u>				
	TO TRANSFER RH REAR DOOR INTERIOR MECHANISM & GLASS TO NEW DOOR.		150.00	60.00
	TO REMOVE AND REFIT RH REAR INTERIOR GARNISHES AND TRIMBOARD TO FACIITATE THE REPAIRS.		280.00	120.00
	TO RMEOVE AND REFIT REAR BUMPER SENSOR .		100.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN RH REAR FENDER INNER PANEL ,RH REAR CHASSIS FRAME ,TO CUT AND WELD RH REAR FENDER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME.		1,500.00	900.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS .		1,500.00	750.00
	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS.		120.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO COMPUTERISE CHECK WHEEL ALIGNMENT.		120.00	60.00
			3,850.00	2,000.00
GRAND TOTAL			12,306.40	9,131.60
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$624.00 NETT)				9,131.60

Report Ref No. CC4/ASM22006069/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.