

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cob

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bal. or Market Value: 887,770k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 25 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 50700 Yr Regn: 11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Prime Mover /

Truck / Trailer or

Make: Toy Prox c.c. 1798

Colour: M.P. White 1st A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB31FU503092915

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Sailun 195/65R15

R: DUN

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 29/5/22

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 23/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

ols Rear, ols Frt & Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got B2

Date/Time, File Pass to?

: Prell. Report
 : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Fixes _____

Others _____

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Not Attached
L1 Rep B

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHC5070D

AAD2206-004

Vehicle No.:
Chassis No.:
UEN No:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

23 JUN 2022

SHC5070D
JTDKB3FU503092915
200303878K
TOYOTA
PRIUS GEN 4
29/05/2022
SCV2858C/CHINA
27/11/2020

PART	LIST	PRICE	STATUS
1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	100.40	?
1 COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	100.40	?
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$	<i>B/B</i> 1,436.60	✓
1 FENDER SUB-ASSY, FRONT RH	\$	<i>R</i> 977.80	✓
1 LINER, FRONT FENDER, RH	\$	<i>L</i> 202.50	✓
1 EMBLEM, SIDE PANEL	\$	<i>R</i> 54.60	✓
1 FENDER SUB-ASSY, FRONT LH	\$	<i>R</i> 977.80	✓
1 LINER, FRONT FENDER, LH	\$	<i>E/M</i> 210.30	✓
1 EMBLEM, SIDE PANEL	\$	<i>N/C</i> 54.60	✓
1 RIM	\$	<i>Rd</i> 1,900.10	✓
1 ABSORBER ASSY, SHOCK, FRONT LH	\$	<i>R</i> 472.30	✓
1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$	<i>R</i> 760.10	✓
1 KNUCKLE, STEERING, LH	\$	<i>R</i> 663.40	✓
1 LINK ASSY, FRONT STABILIZER, LH	\$	<i>M</i> 237.10	✓
1 RIM	\$	<i>Rd</i> 1,900.10	✓
1 ABSORBER ASSY, SHOCK, FRONT RH	\$	<i>R</i> 472.30	✓
1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	760.10	?
1 KNUCKLE, STEERING, RH	\$	663.40	?
1 LINK ASSY, FRONT STABILIZER, RH	\$	237.10	?
1 BAR, STABILIZER, FRONT	\$	353.60	?
1 COVER, FRONT BUMPER	\$	<i>CM</i> 521.00	✓
1 MOULDING, FRONT BUMPER SIDE, RH	\$	<i>M</i> 95.60	✓
1 MOULDING, FRONT BUMPER SIDE, LH	\$	<i>M</i> 95.60	✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>M</i> 110.50	✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	<i>R</i> 716.60	✓
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	<i>R</i> 246.10	✓
1 ABSORBER, FRONT BUMPER, LOWER	\$	<i>M</i> 132.70	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2206-004

SHC5070D

1	ABSORBER, FRONT BUMPER ENERGY	\$	CMY	80.20	✓
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	D19	82.30	✓
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	M17	80.10	✓
1	COVER, ENGINE UNDER, NO.1	\$	CMY	472.40	✓
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$		241.90	?
1	EXTENSION, FRONT BUMPER, LH	\$	R	120.10	X
1	EXTENSION, FRONT BUMPER, RH	\$	R1	120.10	✓
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	R2	47.50	✓
1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	R	47.50	X
1	BRACKET, FRONT BUMPER SIDE, LH	\$	R	59.30	X
1	BRACKET, FRONT BUMPER SIDE, RH	\$	R1	59.30	✓
1	COVER, FRONT BUMPER HOLE, RH	\$	M17	30.20	✓
1	BRACKET, HEADLAMP, RH	\$	R20	34.80	✓
1	BRACKET, HEADLAMP, LH	\$	R20	34.80	✓
1	LAMP ASSY, FOG, LH	\$	M17	237.10	✓
1	LAMP ASSY, FOG, RH	\$		237.10	?
1	UNIT ASSY, HEADLAMP, LH	\$	R20	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	CMY	3,772.50	✓
1	UNIT ASSY, HEADLAMP, RH	\$	R20	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	CMY	3,772.50	✓
1	GRILLE SUB-ASSY, RADIATOR	\$	M17	422.50	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	M17	178.60	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	M17	105.80	✓
1	HOOD SUB-ASSY	\$	R1	983.10	✓
1	HINGE ASSY, HOOD, LH	\$	R2	58.90	✓
1	HINGE ASSY, HOOD, RH	\$	R2	58.90	✓
1	INSULATOR, HOOD	\$	CMY	410.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	R2	78.30	✓
1	LOCK ASSY, HOOD	\$	JM	135.00	✓
1	WIRE, ENGINE ROOM MAIN	\$		7,323.90	?
1	INLET, AIR CLEANER, NO.1	\$		155.60	?
1	INLET, AIR CLEANER, NO.3	\$		42.10	?
1	INLET, AIR CLEANER, NO.2	\$		112.70	?
1	HOSE, AIR CLEANER, NO.1	\$		74.00	?
1	JAR ASSY, WINDSHIELD WASHER	\$	R20	219.10	✓
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	R2	292.40	X
1	INLET SUB-ASSY, WASHER	\$		67.00	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2206-004

SHC5070D

1	CONDENSER ASSY, COOLER	\$	<i>Pr</i> 1,783.20	✓
1	HOSE SUB-ASSY, SUCTION	\$	646.80	?
1	HOSE SUB-ASSY, DISCHARGE	\$	402.90	?
1	PIPE SUB-ASSY, SUCTION	\$	465.80	?
1	SENSOR, AIRCONDITIONER PRESSURE	\$	342.80	?
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	691.00	?
1	COMPRESSOR ASSY, W/MOTOR	\$	4,771.60	?
1	RADIATOR ASSY	\$	<i>Pr</i> 2,218.00	✓
1	TANK ASSY, INVERTER RESERVE	\$	443.00	?
1	COCK ASSY, RESERVE TANK	\$	139.00	?
1	INVERTER WATER PUMP ASSY(W/MOTOR)	\$	518.60	?
1	MOTOR, COOLING FAN, LH	\$	655.10	?
1	MOTOR, COOLING FAN, RH	\$	535.50	?
1	COOLER, MOTOR COOLING	\$	297.20	?
1	WIRE, ENGINE ROOM MAIN	\$	7,323.90	?
1	CLAMP SUB-ASSY, BATTERY	\$	<i>R</i> 115.50	X
1	BATTERY	\$	1,584.90	?
1	JAR ASSY, WINDSHIELD WASHER	\$	<i>Passenger</i> 219.10	X
1	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR	\$	<i>horn</i> 3,869.30	✓
1	AIR BAG ASSY, INSTRUMENT PANEL, LOWER NO.1	\$	<i>Tr</i> 1,907.00	✓
1	AIR BAG ASSY, CURTAIN SHIELD, LH	\$	<i>Boys</i> 1,748.10	✓
1	AIR BAG ASSY, CURTAIN SHIELD, RH	\$	<i>Tr</i> 1,748.10	✓
1	AIR BAG ASSY, FRONT SEAT, RH	\$	<i>Pr</i> <i>Tr</i> 1,008.80	✓
1	AIR BAG ASSY, FRONT SEAT, LH	\$	<i>Tr</i> 1,008.80	✓
1	SENSOR ASSY, SIDE AIR BAG, LH, NO.2	\$	<i>Pr</i> 709.30	✓
1	SENSOR ASSY, SIDE AIR BAG, RH, NO.2	\$	<i>Pr</i> 709.30	✓
1	COMPUTER ASSY, AIR BAG	\$	<i>Pr</i> 1,546.00	✓
1	SENSOR, AIR BAG, FRONT LH	\$	<i>Pr</i> 373.90	✓
1	SENSOR, AIR BAG, FRONT RH	\$	<i>Pr</i> 373.90	✓
1	HEADLINING ASSY, ROOF	\$	<i>Reform</i> 2,125.70	✓
1	BELT ASSY, FRONT SEAT OUTER, RH	\$	<i>Tr</i> 995.10	✓
1	BELT ASSY, FRONT SEAT OUTER, LH	\$	<i>Tr</i> 995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH	\$	<i>Tr</i> 995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH	\$	<i>Tr</i> 995.10	✓
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	<i>Pr</i> 1,300.70	✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	<i>Pr</i> 193.50	X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	<i>Pr</i> 390.60	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2206-004

SHC5070D

1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	926.00	✓
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	321.10	?
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	110.60	✓
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	97.50	✓
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	238.30	✓
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	43.50	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	13.30	✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	1,294.90	✓
1	BOARD SUB-ASSY, REAR DOOR TRIM, RH	\$	556.60	✓
1	GLASS SUB-ASSY, REAR DOOR, RH	\$	410.90	✓
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	293.00	?
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	193.50	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	97.40	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	206.70	^
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	15.40	✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	21.90	✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	98.90	^
1	PANEL SUB-ASSY, QUARTER, RH	\$	871.50	✓
1	LINER, REAR WHEEL HOUSE, RH	\$	139.80	✓
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80	✓
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$	339.60	?
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$	261.00	?
1	COVER, REAR BUMPER	\$	485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70	X
1	GUARD, REAR BUMPER, CENTER	\$	374.50	✓
1	SEAL, REAR BUMPER SIDE, RH	\$	118.30	✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	132.60	✓
1	COVER, REAR BUMPER, LOWER	\$	22.00	✓
1	COVER, DECK TRIM, REAR	\$	126.70	?
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	651.00	X
1	REFLECTOR ASSY, REFLEX, RH	\$	39.00	✓
TOTAL		\$	61,210.80	
25%		\$	15,302.70	

Trans-cab Auto Services Pte Ltd

AAD2206-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5070D

\$ 45,908.10**Special Nett**

1 FRT NUMBER PLATE WITH HOLDER	\$	Nil	140.00	45.00 ✓
1SET BUMPER CLIP FRT	\$	Na	95.00	60.00 ✓
1SET FRNT BUMPER RETAINER CLIP	\$	Na	85.00	X
4L Radiator Coolant	\$	Na	120.00	40.00 ✓
1 HOOD INSULATOR CLIP	\$	Na	55.00	—
1 Engine Under Cover Clip	\$	Na	60.00	—
1 REAR BUMPER SIDE CLIP	\$	Na	60.00	X
1 PARKING AID	\$	Red	700.00	220.00 ✓
1 REAR BUMPER CLIP	\$	Na	85.00	60.00 ✓
1 REAR BUMPER RETAINER CLIP	\$	Na	75.00	X
1/2 FRT FENDER LINER CLIP	\$	Na	130.00	40.00 ✓
1 DOOR STICKER TRANSCAB	\$	Na	100.00	80.00 ✓
1 DOOR STICKER TEL. NO	\$	Na	100.00	60.00 ✓
1 DOOR TRIM CLIP	\$	Na	75.00	X
1 DOOR WEATHERSTRIP CLIP	\$	Na	80.00	—
TOTAL	\$		555.00	
TOTAL PARTS	\$		46,463.10	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	Na	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	100.00 ✓
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	— ✓
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	Na	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2206-004

SHC5070D

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>nn</i> 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>nn</i> 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	<i>100l</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	<i>250l</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>80l</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	<i>210l</i>
Towing Fees	\$	150.00	<i>50l</i>
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	✓
To reinstall rear bumper parking sensor.	\$	170.00	<i>50l</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>50l</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	<i>40l</i>
To replace, refix and top up coolant for radiator	\$	170.00	<i>50l</i>
To lift-up / out engine with gear box and refit.	\$	440.00	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2206-004

SHC5070D

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ *na* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ 380.00 ?

TOTAL \$ **10,290.00**

Over All Total \$ **56,753.10**

(PART-BY-PART) Repair Days **25 DAYS** ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: -

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/05/2022 00:30 (SGT)
Date of Accident	29/05/2022 04:30 (SGT)
Exact Location of Accident	Near TPE, Singapore
Additional Location Information	TPE TOWARDS SLE NEAR SELETAR WEST LINK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5070D
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	Claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variants	5DR HATCHBACK (AUTO)
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1767

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	VFX/P2413997
Cover Note Number	-

DRIVER

Name of Driver	NG POH HENG
NRIC No	SXXXX803Z

Date Of Birth 31/03/1966
 Occupation Outdoor
 Date Of Driving Pass 06/05/1987
 Driving experience 35 YEARS
 Gender Male
 Mobile Number
 Alt. Phone Number (Phone) +65-96926895
 Email Address -
 Address Claims@transcab.com.sg
 Address complement 161A PUNGGOL CENTRAL
 Postcode #18-75
 Is the driver the policyholder? 821161
 If No, Relationship of the Driver with the Insured No
 Does Driver Own Other Vehicles? Hirer
 Vehicle Registration Number of Other Vehicle Owned by Driver No
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? Yes
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name NG BEE CHENG
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Ang Mo Kio North Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18004849999
 Alt. Police Station Phone No (Fax) +65-62181399
 Police Station Address 51 Ang Mo Kio Avenue 9 Singapore 569784
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO : T/20220530/2097

ATTACHMENT(S)


Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Reasons for not uploading a video of the accident SD CARD SEIZED BY TP
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCV2858C

ACCIDENT DIAGRAM

Ver. 30042021



A: SHC5070D

B: SCV2858C

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999



T20220530/2087

2 of 3

Report No. T20220530/2087

CONTINUATION OF REPORT

Driver			
Name	NG POH HENG	ID No.	S17778032
Related Vehicle	SHC50700 (Car)	Contact No.	96926895
Hospital/Clinic	KHOO TECK PHUAT	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	29/05/2022	Date Discharge	30/05/2022
No. of Days granted Medical Leave	07	Degree of Injury	Serious
Passenger			
Name	Ng Bee Cheng	ID No.	F7362017K
Related Vehicle	NIL	Contact No.	82697500
Hospital/Clinic	KHOO TECK PHUAT	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 29/05/2022 at about 0430hrs, I was driving my taxi (SHC50700, Toyota Prius) with one passenger (Ng Bee Cheng, F7362017K) in it along TPE towards SLE. I was driving along the 3rd lane. The car that hit me was driving on the 2nd lane and suddenly turned into my lane and hit the front right door of my car. The impact caused the front of my car to hit the side barriers along the expressway and then spin at the barriers. I don't remember what happened for the first few minutes after the crash. When I regained consciousness after the crash, I saw the other car driver asking me if I was okay but I was unable to answer him as I was still in a state of shock. I did not manage to get the particulars of the other driver as I was having a hard time breathing and needed to calm down. The other driver called ambulance for me and I called the police once I felt better. Ambulance arrived at the scene and I was conveyed to Khoo Teck Phuat Hospital. After which the traffic police arrived and took my particulars and my Memory Card. I was advice by the traffic police to lodge a police report at the nearest NPC for this incident. I was given 7 days of MC from Khoo Teck Phuat hospital for my injuries due to the road traffic incident from 29/05/2022 to 04/06/2022. My car was heavily damaged and I do not know if my car was towed away by my company or traffic police.