

60 Jalan Lam Huat #03-72, Carros Center Singapore 737869

Vehicle number:	SJT7133E
Make and model:	Hyundai Avante
Chassis number:	KMHDU41BMAU94242
Registration Year:	2009

No.	Parts	Qty	Remarks	Amount S\$
1	LH rear door	1		\$ <i>bfr</i> 1,115.00
2	LH rear door protector	1		\$ <i>x</i> 134.00
3	LH rear door protector chrome moulding	1		\$ <i>x</i> 45.20
4	LH rear door frame black sticker	1		\$ <i>net</i> 67.44
5	LH rear door outer handle	1		\$ <i>x</i> 109.00
6	LH rear door outer handle side cover	1		\$ <i>x</i> 32.00
7	LH rear door weatherstrip	1		\$ <i>net</i> 178.20
8	LH rear door lock	1		\$ <i>x</i> 303.00
9	LH rear door lock catch	1		\$ <i>x</i> 46.30
10	LH rear door inner trim board	1		\$ <i>x</i> 703.10
11	LH rear door inner trim board clips	1set		\$ <i>x</i> 50.00
12	Rear windscreen glass rubber moulding	1		\$ <i>x</i> 101.20
13	LH rear fender	1		\$ <i>bul</i> 1,806.90
14	LH rear fender glass with rubber seal	1		\$ <i>net</i> 90.10
15	LH rear fender petrol cover	1		\$ <i>bt</i> 98.30
16	LH rear fender inner trim board	1		\$ <i>x</i> 252.40
17	LH rear fender inner trim board clips	1set		\$ <i>x</i> 50.00
18	LH rear fender splash shield	1		\$ <i>x</i> 89.50
19	LH rear fender splash shield clips	1		\$ <i>x</i> 35.00
20	LH rear fender air duct	1		\$ <i>x</i> 43.50
21	LH rear sport rim	1		\$ <i>aut</i> 845.30
22	LH rear shock absorber	1		\$ <i>x</i> 256.80
23	LH rear wheel bearing	1		\$ <i>x</i> 372.80
24	LH rear knuckle arm	1		\$ <i>x</i> 452.40
25	LH rear trailing arm	1		\$ <i>x</i> 245.60
26	LH taillamp assy	1		\$ <i>crq</i> 303.20
27	LH taillamp panel	1		\$ <i>x</i> 177.60
28	LH taillamp sponge gasket	1		\$ <i>x</i> 36.00
29	LH taillamp lock clips	1set		\$ <i>x</i> 30.00
30	Rear bumper	1		\$ <i>tn</i> 489.60
31	Rear bumper clips	1set		\$ <i>net 30</i> 50.00
32	Rear bumper RH side retainer	1		\$ <i>x</i> 56.20
33	Rear bumper LH side retainer	1		\$ <i>x</i> 56.20
34	Bootlid LH lamp	1		\$ <i>em</i> 231.80
	Bootlid "Avante" emblem	1		\$ <i>id</i> 23.10
	Bootlid centre emblem	1		\$ <i>x</i> 33.80

Parts Sub Total:	\$	9,010.54
Less 20%:	\$	1,802.11
Parts Total:	\$	7,208.43

No.	Special Nett	Qty	Remarks	Amount S\$
1	LH rear fender glass with rubber seal	1		\$ 80.00

2	LH rear fender joint seal	1		\$ 400 75.00
3	LH rear tyre	1		\$ X 550.00
4	Brake fluid	1		\$ X 70.00
5	Rear windscreen glass sealant	1		\$ 600 70.00
6	Rear windscreen glass inner seal	1		\$ X 50.00
7	LH taillamp panel	1		\$ X 30.00
8	Rear bumper lower spoiler	1		\$ 600 300 850.00
9	LH side rocker panel spoiler	1		\$ 600 300 750.00
10	Bootlid RH emblem	1		\$ X 70.00
11	Bootlid LH emblem	1		\$ X 70.00
Special nett total:				\$ 2,665.00

No.	Labour, painting and misc	Amount S\$
1	Labour charges on affected and consistent areas and panels	\$ 700 2,200.00
2	Putty and re-spray on affected areas and panels	\$ 800 1,800.00
3	Check wiring and lighting system	\$ 30 80.00
4	Spray rust chemical on affected areas	\$ 30 150.00
5	Remove and reinstall rear windscreen glass to assist repair	\$ 120 220.00
6	Remove and replace LH rear door inner components to assist repair	\$ 60 150.00
7	Remove and reinstall fuel tank, hoses and sensor to assist repair	\$ 60 250.00
8	Remove and replace rear undercarriage parts to assist repair	\$ X 550.00
9	Remove and reinstall rear bumper reverses sensors to assist repair	\$ 30 180.00
10	Remove and reinstall LH rear fender glass to assist repair	\$ 60 150.00
11	Conduct and adjust wheel alignment system	\$ 80 120.00
12	Remove and replace roof lining, seats, carpet and trims to assist repair	\$ 60 450.00
Labour total:		\$ 6,300.00

Tanpin 97495749
 WP 29/6/22 450 pm
 4/5 Resurvey after repair
 Tanpin @ 1/10/2022
 6 days

Parts total: \$ 7,208.43
 Special nett total: \$ 2,665.00
 Labour total: \$ 6,300.00
 Grand total: \$ 16,173.43

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: