

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 21 October 2022 4:16 PM
To: Wai Yin Ng
Subject: RE: HLA-TP SHC 5661Z DOA: 23/06/2022

Dear Wai Yin,

WITHOUT PREJUDICE

The repair cost should be \$4217.40 before GST.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wai Yin Ng <waiyin.ng@transcab.com.sg>
Sent: Friday, 21 October 2022 4:13 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: Re: HLA-TP SHC 5661Z DOA: 23/06/2022

Without prejudice

Dear Shiau Chan

Based on marked estimate, the correct calculation should be \$4,217.40 (before GST).

AAD2206-105		
SHC5661Z DOA 23.06.22		
PART	\$	485.60
	\$	332.70
	\$	374.50
	\$	22.00
	\$	54.60
	\$	54.60
	\$	47.90
	\$	913.60
SUPPLEMENTAR	\$	1,147.80
	\$	229.90
	\$	3,663.20
25%	\$	915.80
	\$	<u>2,747.40</u>
S.NETT	\$	60.00
	\$	30.00
	\$	30.00
	\$	220.00
	\$	<u>340.00</u>
LABOUR	\$	400.00
	\$	660.00
	\$	50.00
	\$	20.00
	\$	<u>1,130.00</u>
	\$	4,217.40
FINALISE	\$	4,217.40

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63

Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, October 19, 2022 2:28 PM
To: Wai Yin Ng <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: HLA-TP SHC 5661Z DOA: 23/06/2022

Dear Wai Yin,

Re-send.

Any updates?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Thursday, 22 September 2022 10:54 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: HLA-TP SHC 5661Z DOA: 23/06/2022

Dear Wai Yin,

Re-send.

Any updates?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, 6 September 2022 3:25 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: HLA-TP SHC 5661Z DOA: 23/06/2022

Dear Wai Yin,

Any status?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Friday, 12 August 2022 10:20 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: HLA-TP SHC 5661Z DOA: 23/06/2022

Dear Wai Yin,

Any updates?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, 12 July 2022 5:46 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: HLA-TP SHC 5661Z DOA: 23/06/2022

Dear Wai Yin,

WITHOUT PREJUDICE

We will be advising our Principal a cost of repair of final figure \$4,214.70 with 3 days of repair, subject to their approval.

Kindly check.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)