

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Updated 11 Feb 2020

DATE: 17.06.22
 MODEL: Hyundai Ioniq (Front)
 VEHICLE NO.: SHA7090T

D.O.A 17.06.22
 INSURANCE: NTUC (Ysun)
 MVA: JUMANI

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	FRT BUMPER			\$ 481.10 <i>all</i>
	FRT FENDER LH			\$ 588.80 <i>bt</i>
	FRT FENDER LH - EMBLEM			\$ 26.60 <i>wa</i>
	HEADLAMP ASSY RH			\$ 2,110.30 <i>we</i>
	FRT BUMPER CTR MOULDING			\$ 368.50 <i>xm</i>
	FRT WHEEL CAP LH			\$ 346.40 <i>cur</i>
	FRT BUMPER SIDE BRACKET LH			\$ 41.40 <i>Xun</i>
	FRT BUMPER CLIPS	10		\$ 22.00 <i>wa</i>
	SUB TOTAL		3575.20	\$ 3,985.10
	LESS 20%		2860.16	\$ 797.02
	DISCOUNTED TOTAL			\$ 3,188.08
	SUB TOTAL			
	<u>Labour Charge</u>			
	Panel Beating			\$ 800.00 <i>350</i>
	Spray Painting Charge			\$ 600.00 <i>500</i>
	Wiring Charge			\$ 50.00 <i>30</i>
	Tuff Kote			\$ 50.00 <i>30</i>
	Advertisement logo - Fender			\$ 100.00 <i>cut</i>
	TOTAL LABOUR		1610	\$ 1,600.00
	ESTIMATE TOTAL		3870.16	\$ 4,788.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 9749 5747
wp 17/6/22 @ 2:40pm
1/15 Ready after repair
2 days
Tanpin 9749 5747