

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 22/06/2022

Estimated repair cost for vehicle no: GBJ8135R HIACE VAN TURBO 5DR MT

CHASSIS: JTFHT02PX00249448 (2019)

27/06/2022

TP AXA

Xiao Tony

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Defect</i>	\$658.00	\$658.00 ✓
2	1	FRONT BUMPER REINFORCEMENT <i>Defect</i>	\$548.00	\$548.00 ✓
3	1	FRONT BUMPER BEAM <i>Not in</i>	\$289.00	\$289.00 +
4	1	FRONT BUMPER SIDE RETAINER LH <i>Crack</i>	\$128.00	\$128.00 ✓
5	1	FRONT BUMPER SIDE GRILLE COVER LH <i>Crack</i>	\$154.00	\$154.00 75
6	1	FRONT BUMPER LOWER GRILLE <i>Crack</i>	\$120.00	\$120.00 ✓
7	1	LH FRONT STEP GARNISH <i>Defect</i>	\$189.00	\$189.00 ✓
8	1	LH FRONT CORNER PANEL <i>Defect</i>	\$371.1	\$371.1 ✓
9	1	LH FRONT CORNER PANEL BRACKET <i>Crack</i>	\$65.00	\$65.00 ✓
10	1	BONNET <i>Rep</i>	\$598.00	\$598.00 +
11	1	BONNET HINGE <i>Not in</i>	\$154.00	\$154.00 +
12	1	FRONT WIPER TANK <i>Not in</i>	\$195.00	\$195.00 ✓
13	1	FRONT WIPER GARNISH <i>Not in</i>	\$358.00	\$358.00 +
14	1	FRONT GRILLE <i>Crack</i>	\$384.00	\$384.00 ✓
15	1	FRONT GRILLE BASE <i>Crack</i>	\$214.00	\$214.00 ✓
16	1	FRONT SUPPORT PANEL <i>Not in</i>	\$578.00	\$578.00 +
17	1	LH FRONT HEADLAMP <i>Crack</i>	\$2584	\$2584 1300(SW)
18	1	LH FRONT HEADLAMP LOWER BRACKET <i>Not in</i>	\$41.00	\$41.00 +
19	1	LH FRONT DOOR <i>Defect</i>	\$1,208.00	\$1,208.00 ✓
20	1	LH FRONT DOOR INNER TRIM BOARD <i>Not in</i>	\$445.00	\$445.00 +
21	2	LH FRONT DOOR HINGE <i>Not in</i>	\$156.00	\$156.00 +
22	1	LH FRONT DOOR CHECKER <i>Not in</i>	\$98.00	\$98.00 +
23	1	LH FRONT DOOR WEATHER STRIPE <i>Not in</i>	\$154.00	\$154.00 +

24 1 LH Front door wire harness cover

25 1 LH Front door step panel

26 1 LH Front door pillar (outer)

TOTAL : \$7,373.00

LESS 25 % \$1,843.25

SUB-TOTAL : \$5,529.75

AXA

3811625

S-N: 1500

GBJ8135R HIACE VAN TURBO 5DR MT

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	LH FRONT HEADLAMP OUTER GARNISH <i>lot</i>	\$180.00	\$180.00 <i>100</i>
2	1	LH FRONT DOOR LTA STICKER <i>2x1</i>	\$45.00	\$45.00 ✓
3	1	FRONT BUMPER CLIPS <i>2x1</i>	\$80.00	\$80.00 <i>50</i>
4	1	FRONT GRILLE CLIPS <i>2x1</i>	\$80.00	\$80.00 <i>20</i>
5	1	FRONT NUMBER PLATE <i>2x1</i>	\$45.00	\$45.00 <i>+</i>

195

TOTAL: \$430.00

TOTAL PARTS: \$5,959.75

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & TRANSFER ALL LH DOOR FITTING

800
~~\$1,200.00~~
1840 ~~\$1,000.00~~ *800*
~~\$80.00~~ *30*
~~\$300.00~~ *80*
~~\$300.00~~ *80*

Subtotal :- \$2,880.00

Total:- \$8,839.75

Adrian Lij
L/S 27/06/22

05 Days.

total 6651.25

L/S: \$3K

5.3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: