

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22006101/TCY3Q2**Date:** 15/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000208		
Claimant Vehicle No :	SH7204R	Insured Vehicle No :	SLP247D		
Date of Loss:	24/06/2022	Nature of Claim:	TP	Claim No:	M2203310

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7204R	Engine No:	2ZR2C16578
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKB3FU603080546
Reg. Date:	15/05/2019 (Man. Year: 2018)	Odometer:	238541 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,448.42	1,311.62	1,136.80	46.43
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,520.00	880.00	640.00	42.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,979.42	2,202.62	1,776.80	44.65
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	3,979.42	1,750.00	2,229.42	56.02
+ GST 7.00/7.00% (S\$)	278.56	122.50	156.06	56.02
Nett Amount (S\$)	4,257.98	1,872.50	2,385.48	56.02

INSPECTION

Date of Assignment:	27/06/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/06/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Sep 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH7204R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK OUTER GARNISH	Repair	1,054.71 FL	*- FL
2	1		*REAR TRUNK PRIUS	Necessary	62.14 FL	*62.14 FL
3	1		*REAR TRUNK HYBRID	Necessary	62.14 FL	*62.14 FL
4	1		*REAR TRUNK TOYOTA STAR	Necessary	81.43 FL	*81.43 FL
5	1		*REAR BUMPER	Deformed	551.89 FL	*551.89 FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
7	1		*REAR BUMPER LOWER COVER-BLACK	Deformed	654.96 FL	*654.96 FL
8	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
9	1		*REAR BUMPER TOW COVER	Not Necessary	82.70 FL	*- FL
10	1		*REVERSE SENSORS	Not Working	135.70 F	*135.70 F
11	1		*REAR TRUNK COMFORTDELGRO	Necessary	30.00 F	*30.00 F
12	1		*REAR TRUNK 65521111	Necessary	30.00 F	*30.00 F
13	1		*REAR TRUNK APPS	Necessary	40.00 F	*40.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,185.99	1,670.26
- List Item Discount on L Items 25.00/25.00% (\$\$)	737.57	358.64
Total Parts (\$\$)	2,448.42	1,311.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			1,520.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >