

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006102/DVY3Q2**Date:** 14/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00005402200	
Claimant Vehicle No :	SLQ3528T	Insured Vehicle No :	YN2799X	
Date of Loss:	29/05/2022	Nature of Claim:	TP	Claim No: SNM22D204287/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3528T		Engine No:	LEB5918381
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)		Chassis No:	RU31218370
Reg. Date:	05/07/2017 (Man. Year: 2016)		Odometer:	310395 km
Colour:	Blue			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,510.08	2,571.12	20,938.96	89.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	1,250.00	5,150.00	80.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,910.08	3,821.12	26,088.96	87.22
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	29,910.08	3,000.00	26,910.08	89.97
+ GST 7.00/7.00% (\$\$)	2,093.71	210.00	1,883.71	89.97
Nett Amount (\$\$)	32,003.79	3,210.00	28,793.79	89.97

INSPECTION

Date of Assignment:	27/06/2022	
Date Inspected:	28/06/2022 Inspected At:	C. S. Ong Auto Pte Ltd (HQ) BLK 10 ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3528T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	801.70 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	35.00 FL	*- FL
3	1		*FRONT BUMPER LOWER	Not Necessary	491.00 FL	*- FL
4	1		*FRONT BUMPER LOWER LID	Not Necessary	381.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	510.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP HOLDER RH	Not Necessary	70.00 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	980.00 FL	*- FL
8	1		*FRONT FENDER LH	Dented	780.30 FL	*580.00 FL
9	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	142.30 FL	*- FL
10	1		*FRONT FENDER ARC GARNISH LH	Not Necessary	320.00 FL	*- FL
11	1		*SIDE MIRROR ASSY LH	Broken	1,984.50 FL	*874.50 FL
12	1		*FRONT SPORTS RIM LH	Not Necessary	980.00 FL	*- FL
13	1		*FRONT WHEEL BEARING & HUB ASSY LH	Not Necessary	338.30 FL	*- FL
14	1		*FRONT KNUCKLE ARM LH	Not Necessary	430.10 FL	*- FL
15	1		*FRONT ABSORBER LH	Not Necessary	520.19 FL	*- FL
16	1		*FRONT LOWER ARM LH	Not Necessary	485.00 FL	*- FL
17	1		*FRONT DOOR LH	Repair	1,830.50 FL	*- FL
18	1		*FRONT DOOR WINDOW GLASS LH	Not Necessary	978.20 FL	*- FL
19	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	234.00 FL	*- FL
20	1		*FRONT DOOR PILLAR BLACK STICKER LH	Not Necessary	98.20 FL	*- FL
21	1		*FRONT DOOR WEATHER STRIP INNER LH	Not Necessary	384.59 FL	*- FL
22	1		*FRONT DOOR WEATHER STRIP OUTER LH	Not Necessary	399.20 FL	*- FL
23	2		*FRONT DOOR HINGE	Not Necessary	204.80 FL	*- FL
24	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	894.59 FL	*- FL
25	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	784.20 FL	*- FL
26	1		*FRONT DOOR POWER WINDOW REGULATOR LH	Not Necessary	327.80 FL	*- FL
27	1		*FRONT DOOR LOCK LH	Not Necessary	312.40 FL	*- FL
28	1		*FRONT DOOR HANDLE LH	Not Necessary	423.10 FL	*- FL
29	1		*REAR DOOR LH	Not Necessary	1,820.50 FL	*- FL
30	1		*REAR DOOR WINDOW GLASS LH	Not Necessary	978.20 FL	*- FL
31	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	231.00 FL	*- FL
32	1		*REAR DOOR WEATHER STRIP INNER LH	Not Necessary	384.59 FL	*- FL
33	1		*REAR DOOR WEATHER STRIP OUTER LH	Not Necessary	399.20 FL	*- FL
34	1		*REAR DOOR BLACK PILLAR STICKER LH	Not Necessary	98.20 FL	*- FL
35	2		*REAR DOOR HINGE	Not Necessary	204.80 FL	*- FL
36	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	768.30 FL	*- FL
37	1		*REAR DOOR POWER WINDOW REGULATOR LH	Not Necessary	327.80 FL	*- FL
38	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	813.70 FL	*- FL
39	1		*REAR DOOR LOCK LH	Not Necessary	217.40 FL	*- FL
40	1		*REAR FENDER LH	Not Necessary	1,984.24 FL	*- FL
41	1		*REAR FENDER ARC GARNISH LH	Not Necessary	274.00 FL	*- FL
42	1		*LOWER SIDE SKIRT LH	Not Necessary	1,035.70 FL	*- FL
43	1		*LOWER ROCKER PANEL LH	Not Necessary	1,298.70 FL	*- FL
44	1		*FRONT LH HEADLAMP	Mtg Cracked	1,980.30 FL	*1,759.40 FL
45	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*REAR DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

10/14/22, 3:05 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
50	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					29,297.60	3,213.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					5,787.52	642.78
Total Parts (\$\$)					23,510.08	2,571.12
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,600.00	500.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	700.00
3	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
4	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
5	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
7	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	200.00	0.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
9	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	New	200.00	20.00
Gross Labour Cost (\$\$)			6,400.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >