

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 21 Jul 2022

Preliminary Advice

| | | | |
|--------------------|-----------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SDE3083S | Accident Date | : 22/06/2022 |
| TP Vehicle No | : SLX1673H | Assignment Date | : 27/06/2022 |
| Make | : HONDA VEZEL | Est. Duration of Repair | : 04 |
| Date of Inspection | : 28/06/2022 | | |
| Inspection At | : LEE BROTHERS AUTOMOTIVE PTE LTD | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 9,840.04 |
| Revised Amount | :S\$ | 4,263.48 |
| Check Items (Estimated) | :S\$ | |
| Total | :S\$ | 4,263.48 |
| Lump Sum Repair | :S\$ | 3,400.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a "Without Prejudice" basis.
Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.