

SGV1080M 2015 April

TP Sompoo
Veron.

Mercedes Benz C200 1991cc
WDD2050422F047334

Rear Bumper	Distorted	1668	✓
Rear Bumper Clips.	x12	50(SN)	✓
Rear Bumper Side Holder	x02 Damaged	78x2 = 156.	✓
Rear Bumper Lower Garnish.	Deformed	385	✓
Rear Bumper Lower Garnish Chrome Moulding.	cut	228	✓
Rear Bumper Reinforcement	Dented	685	✓
Rear Bumper Centre Guide	Crushed	198	✓
Rear Bumper Under Cover RH.	torn	175	✓
Rear Bumper Bracket	x 02 Damaged	68x2 = 136.	✓
Rear Bumper Under Cover Centre	x1 nr	274.	x.
Reverse Sensor	x 04 2 pieces. damaged	250x4 = 1000	500.
Reverse Sensor Wire Harness.	x1 nr	435	x.
Rear End Panel	Repair	1260	x
Rear End Panel Top Garnish.	crushed	263	✓
Rear End Panel Top Garnish Clips.	x12	20(SN)	✓

SGV1080M.

Rear End Panel Sealant.	HP m	60(SN) X.
Taillamp x 02	RH crub'd	585 x 2 = 1170 S85
Taillamp lower Bracket x 02	crub'd	68 x 2 = 136. ✓
Bootlid	Dented.	2170 ✓
Bootlid Lock	Damd	322 ✓
Bootlid Weatherstrip.	XHP m	245 X.
Bootlid Chrome Moulding.	XHP m	208 X.
Mercedes Benz Logo	} New	90. ✓
C200 Emblem.		85 ✓

Front Number Plate	Dented	30(SN) ✓
Front Number Plate Holder	Deformed	30(SN) ✓
Front Number Plate Garnish.	Deformed	92 ✓
Front Bumper	Deformed	1636. ✓
Front Bumper Clips.	New	50(SN) ✓
Front Bumper Sensor	x 02 HP m	250 x 2 = 500. X.

SGV1080M.

Front Bumper Side Holder x 02 ^{HP} _m

85x2=170 *

Front Bumper lower Grille } ^{HP} _m
Front Bumper Reinforcement }

262 *

645 *

155 ✓

Front Bumper Sponge. Included

758 ✓

Front Grille Included

20(SN) ✓

Front Grille Clips. ^{HP} _m

128 ✓

Front Grille Logo. ^{HP} _m

3440x4=6880 X

Handling x 02 ^{HP} _m

10551

S-N: 2w.

9495.90

Panel Beating

~~1600~~ 900

Spray Painting,

~~1400~~ 900

Wiring

~~1000~~ 60

To remove front bumper sensors.

~~1000~~ 50

To remove reverse sensors.

~~1000~~ 50

To spray buff coat

~~1500~~ 40

To remove upholstery.

~~1500~~ 60.

SGV1080M.

To remove rear camera.

To transfer bootlid fittings

To perform diagnostic test.

~~100~~ 50

~~150~~ 60

~~200~~ 150

450

2320

26,855.00

total: 12015.80

h/s: 9.6K.

08 Days.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: