

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Jul 2022

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : GX4539C | Accident Date | : 21/06/2022 |
| TP Vehicle No | : GBA4753E | Assignment Date | : 27/06/2022 |
| Make | : TOYOTA DYNA 1.5T | Est. Duration of Repair | : 4 |
| Date of Inspection | : 29/06/2022 | | |
| Inspection At | : KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 SINGAPORE 408701 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 6,256.79 |
| Revised Amount | :S\$ | 2,485.80 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 2,485.80 |
| Lump Sum Repair | :S\$ | 1,900.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.