



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION (TP)		Ref:	CS/SPF22006119/Kvy3m4
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROAD SINGAPORE 438675		Date:	06/07/2022
ATTN: HAFIZUL FARHAN		Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 1009S	Veh. Inspected	SGF 70H
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/008	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	27/06/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH604573249	Colour	METALLIC PEARL WHITE
Odometer	130735 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	PIRELLI	7 mm
L/H Front Tyre	225/40 R18	PIRELLI	7 mm
R/H Rear Tyre	225/40 R18	PIRELLI	7 mm
L/H Rear Tyre	225/40 R18	PIRELLI	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	27/01/2022	Inspection Date	29/06/2022
Survey held at	No.5, Kim Chuan Lane Singapore 537070		
Repairer	WORLD AUTO PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	