

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

7P111

Asher.

ESTIMATE OF REPAIR

Veh# : SJH4751D

Model:

Honda fit 1.3GA

Accident Date : 26/6/2022

8/8/2008 7/8/2023

Location : CTE TOWARDS CITY BEFORE BRADELL ROAD EXIT

3P:

SNB184B (III)

GE610S6832

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Distorted</i>	581.40	495	
2	10pcs	Rear bumper clips <i>re</i>		30.00	✓
3	2pcs	Rear bumper screw clips <i>new</i>		20.00	+
4	2pcs	Rear bumper o/s & n/s retainer <i>Dented</i>	82.40	✓	
5	2pcs	Rear reverse sensor <i>Dented</i>		280.00	<i>200</i>
6	1pc	Rear end panel <i>Dented</i>	381.90	✓	
7	2 pcs	Rear o/s & n/s stay <i>new</i>	154.20	+	
8	1pc	Rear end panel inner trim <i>Dented</i>	103.50	✓	
9	4pcs	Rear end panel inner trim clips <i>re</i>		16.00	✓
10	2pcs	Rear o/s & n/s tail lamp <i>Cracked</i>	878.20	<i>590</i>	
11	2pcs	Rear o/s & n/s tail lamp panel <i>Replaced Lit Dented</i>	363.80	<i>+ 181.50</i>	
12	2pcs	Rear o/s & n/s tail lamp sealant <i>new</i>	80.00	+	
13	2pcs	Rear Regn. No. Plate lamp <i>new</i>	107.20	+	
14	1pc	Rear boot cover <i>Dented</i>	871.50	✓	
15	1pc	Rear boot cover weatherstrip <i>at</i>	114.40	✓	
16	1pc	Rear boot cover emblem <i>new</i>	61.50	<i>40</i>	
17	1pc	Rear boot cover 'FIT' emblem <i>new</i>	61.70	<i>45</i>	
18	1pc	Rear boot cover inner trim <i>new</i>	182.25	✓	
19	11pcs	Rear boot cover inner trim clips <i>new</i>		33.00	✓
20	4pcs	Rear boot cover o/s & n/s stopper <i>new</i>	74.00	+	
21	1pc	Rear boot cover moulding <i>new</i>	187.10	+	
22	4pcs	Rear boot cover moulding clips <i>new</i>		16.00	+
23	1pc	Rear boot cover lock (Upper) <i>Dented</i>	291.60	✓	
24	1pc	Rear boot cover lock (Lower) <i>new</i>	43.10	✓	
25	2 pcs	Rear o/s & n/s fender inner trim <i>cracked</i>	860.40	<i>610</i>	
26	18 pcs	Rear o/s & n/s fender inner trim clips <i>new</i>		54.00	✓
27	1 pc	Rear windscreen sealant <i>new</i>		80.00	<i>60</i>
28	1 pc	Rear windscreen moulding <i>new</i>		50.00	✓
29	1 pc	Rear regn. no. plate <i>new</i>		45.00	+
30	1 pc	Front bumper <i>Dented</i>	580.90	<i>485</i>	
31	10 pcs	Front bumper clips <i>new</i>		30.00	✓
32	1 pc	Front bumper lower lip <i>Dented</i>		600.00	<i>500</i>
33	1 pc	Front bumper insulator <i>new</i>	94.20	+	
34	1 pc	Front bumper enforcement <i>Dented</i>	146.70	✓	

35	2 pcs	Front bumper o/s & n/s retainer <i>new</i>	86.60	✓	
36	1 pc	Front bumper grille (Lower) <i>new</i>	196.60	✓	
37	1 pc	Front grille <i>crackd</i>	236.70	✓	
38	1 pc	Front grille emblem <i>new</i>	71.70	45	
39	6 pcs	Front grille clips <i>new</i>		18.00	✓
40	1 pc	Front bonnet <i>Buckled</i>	750.30	✓	
41	4 pcs	Front bonnet o/s & n/s rubber stopper <i>new</i>	160.00	+	
42	2 pcs	Front o/s & n/s head lamp <i>crackd</i>	1,596.80	1246	
43	2 pcs	Head lamp bracket <i>crackd</i>	82.40	✓	
44	1 pc	Front support panel <i>Buckled</i>	696.80	✓	
45	1 pc	Front brace panel <i>new</i>	269.70	+	
46	1 pc	Radiator <i>new</i>	761.20	+	
47	1 pc	Coolant <i>waspped new</i>		80.00	40
48	1 pc	Condenser <i>waspped</i>	810.50	✓	
49	1 pc	Front reg. no. plate <i>3 in 1</i>		45.00	+
50	1 pc	Front reg. no. plate bracket <i>new</i>		29.00	+
		<i>8813.15 S.N: 1031</i>	Sub Total:	12,021.25	1426.00 0.00
		<i>7050.52</i>		20%	0% 10%
			After Less %:	9,617.00	1426.00 0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.	2,200.00	1800	
2		To spray painting.	1,600.00	1400	
3		To re align rear chassis frame.	200.00	+	
4		To remove & replace rear exhaust.	100.00	+	
5		To remove & refit rear windscreen	140.00	120	
6		To remove & refit rear upholstery to facilitate repair	50.00	✓	
7		To remove and replce rear tail gate <i>ittings</i>	120.00	60	
8		To remove & replace radiator.	80.00	60	
9		To remove and replace condenser & top up gas	80.00	60	
10		To re set electrical system.	180.00	60	+
11		To check wiring.	100.00	60	
12		To re seal anti rust.	100.00	✓	
		Sub Total:	4,950.00		
		Total:	15,993.00		
		After Less 20%:	12,794.40		

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Adrian L
2/3 28/06/22
14 Days.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mobil 1



Total: 11791.52

2/3: 8K (Nett Value)