

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5962E*Not Notion
1/1mp &***AAD2206-**

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 JUN 2022**SHC5962E**

JTDKB3FU703092494

200303878K

TOYOTA

PRIUS GEN 4

23/06/2022

SDH9208U/AIG

30/09/2021

PART**LIST**

- 1 COVER SUB-ASSY, FRONT PILLAR, UPR RH
- 1 COVER SUB-ASSY, FRONT PILLAR, UPR LH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 COVER, FRONT BUMPER
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 MOULDING, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 COVER, ENGINE UNDER, NO.1
- 1 COVER SUB-ASSY, ENGINE UNDER, NO.2
- 1 EXTENSION, FRONT BUMPER, LH
- 1 EXTENSION, FRONT BUMPER, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER, FRONT BUMPER HOLE, RH

\$	Pa	100.40	X
\$	Pa	100.40	X
\$	Bu	977.80	✓
\$	CM	202.50	✓
\$	Mc	54.60	✓
\$	R	977.80	X
\$	Pa	210.30	X
\$	na	54.60	X
\$	Ta	521.00	✓
\$	mi	95.60	✓
\$	Pa	95.60	X
\$	mi	110.50	✓
\$	Bj	716.60	✓
\$	Bj	246.10	✓
\$	CM	132.70	✓
\$	CM	80.20	✓
\$	mi	82.30	✓
\$	CM	80.10	✓
\$	CM	472.40	✓
\$		241.90	✓
\$	R	120.10	X
\$	Rj	120.10	✓
\$	mi	47.50	✓
\$	Pa	47.50	X
\$	R	59.30	X
\$	Rj	59.30	✓
\$	mi	30.20	✓

Trans-cab Auto Services Pte Ltd**AAD2206-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5962E

1	BRACKET, HEADLAMP, RH	\$	CM	34.80	✓
1	BRACKET, HEADLAMP, LH	\$	Ln	34.80	X
1	LAMP ASSY, FOG, LH	\$		237.10	?
1	LAMP ASSY, FOG, RH	\$	mit	237.10	✓
1	UNIT ASSY, HEADLAMP, LH	\$	my CM	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$		3,772.50	?
1	UNIT ASSY, HEADLAMP, RH	\$	Bu	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$		3,772.50	?
1	GRILLE SUB-ASSY, RADIATOR	\$	CM	422.50	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	CM	178.60	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	mit	105.80	✓
1	HOOD SUB-ASSY	\$	Bu	983.10	✓
1	HINGE ASSY, HOOD, LH	\$	R1	58.90	✓
1	HINGE ASSY, HOOD, RH	\$	R1	58.90	✓
1	INSULATOR, HOOD	\$	Ln	410.90	X
1	BRACE, HOOD LOCK SUPPORT	\$	R1	78.30	✓
1	LOCK ASSY, HOOD	\$	D1	135.00	✓
1	WIRE, ENGINE ROOM MAIN	\$		7,323.90	?
1	INLET, AIR CLEANER, NO.1	\$		155.60	?
1	INLET, AIR CLEANER, NO.3	\$		42.10	?
1	INLET, AIR CLEANER, NO.2	\$		112.70	?
1	HOSE, AIR CLEANER, NO.1	\$		74.00	?
1	JAR ASSY, WINDSHIELD WASHER	\$	ru	219.10	✓
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$		292.40	?
1	INLET SUB-ASSY, WASHER	\$		67.00	?
1	CONDENSER ASSY, COOLER	\$		1,783.20	?
1	HOSE SUB-ASSY, SUCTION	\$		646.80	?
1	HOSE SUB-ASSY, DISCHARGE	\$		402.90	?
1	PIPE SUB-ASSY, SUCTION	\$		465.80	?
1	SENSOR, AIRCONDITIONER PRESSURE	\$		342.80	?
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$		691.00	?
1	COMPRESSOR ASSY, W/MOTOR	\$		4,771.60	?
1	RADIATOR ASSY	\$		2,218.00	?
1	TANK ASSY, INVERTER RESERVE	\$		443.00	?
1	COCK ASSY, RESERVE TANK	\$		139.00	?
1	INVERTER WATER PUMP ASSY(W/MOTOR)	\$		518.60	?
1	MOTOR, COOLING FAN, LH	\$		655.10	?

Trans-cab Auto Services Pte Ltd

AAD2206-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5962E

1	MOTOR, COOLING FAN, RH	\$	535.50	?
1	COOLER, MOTOR COOLING	\$	297.20	?
1	WIRE, ENGINE ROOM MAIN	\$	7,323.90	?
1	CLAMP SUB-ASSY, BATTERY	\$	115.50	x
1	BATTERY	\$	1,584.90	x
1	JAR ASSY, WINDSHIELD WASHER	\$	219.10	?
1	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR	\$	3,869.30	?
1	AIR BAG ASSY, INSTRUMENT PANEL, LOWER NO.1	\$	1,907.00	—
1	AIR BAG ASSY, CURTAIN SHIELD, LH	\$	1,748.10	—
1	AIR BAG ASSY, CURTAIN SHIELD, RH	\$	1,748.10	—
1	SENSOR ASSY, SIDE AIR BAG, LH, NO.2	\$	709.30	—
1	SENSOR ASSY, SIDE AIR BAG, RH, NO.2	\$	709.30	—
1	COMPUTER ASSY, AIR BAG	\$	1,546.00	—
1	SENSOR, AIR BAG, FRONT LH	\$	373.90	—
1	SENSOR, AIR BAG, FRONT RH	\$	373.90	—
1	HEADLINING ASSY, ROOF	\$	2,125.70	—
1	BELT ASSY, FRONT SEAT OUTER, RH	\$	995.10	—
1	BELT ASSY, FRONT SEAT OUTER, LH	\$	995.10	—
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH	\$	995.10	—
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH	\$	995.10	—
TOTAL		\$	51,354.60	
25%		\$	12,838.65	
		\$	38,515.95	

Special Nett

1	FRT NUMBER PLATE WITH HOLDER	\$	140.00	455n
1SET	BUMPER CLIP FRT	\$	95.00	605n
1SET	FRNT BUMPER RETAINER CLIP	\$	85.00	x
4L	Radiator Coolant	\$	120.00	305n
1	HOOD INSULATOR CLIP	\$	55.00	x
1	Engine Under Cover Clip	\$	60.00	—
2	FRT FENDER LINER CLIP	\$	130.00	45
TOTAL		\$	555.00	

TOTAL PARTS \$ 39,070.95**LABOUR**

Trans-cab Auto Services Pte Ltd**AAD2206-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5962E

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	9001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	?
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	1001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	901
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	13201
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

Trans-cab Auto Services Pte Ltd

AAD2206-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5962E

To replace, refix and top up coolant for radiator	\$	170.00	5d
To lift-up / out engine with gear box and refit.	\$	440.00	?
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	5d
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	?
TOTAL	\$	9,390.00	
Over All Total	\$	48,460.95	

(PART-BY-PART) Repair Days**25 DAYS**

13 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: