



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911		
			Document No. 0				
			Document Date 27/06/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:SP2001891658 ACC DATE:27.06.2022 TOW IN:26.06.2022 EXCESS: DATE-IN:26.06.2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON: 200.00				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)					122.40
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP					180.00
4	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR					180.00
5	B	BP-LAB2 TO RESET ECU AND REPROGRAMME					180.00
6	B	BP-LAB2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR					360.00
7	S	BP-SUBLET R/I AC CONDENSOR, PIPING AND REGAS					80.00
8	L	BP-LPO SUPPLY REGN PLATE (PO#)					4320.00
9	B	BP-LAB2 REPLACE ACC DAMAGED PARTS 770 X 8 4 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				2850	4130.00
10	B	BP-RES2 RESPRAY ACC AFFECTED AREAS 590 X 5	1.00	581.40			581.40
11	1	S52119-0X951 COVER, FR BUMPER, L / BR	1.00	71.90			71.90
12	2	S53395-06110 SEAL, HOOD TO FR END 1 / TH					
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details					
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ	Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911					
		Document No.						
		0						
		Document Date						
		27/06/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	0.00		0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
13	3	S52114-06460	BRACKET, FR BUMPER E (Camber plate hll) - BR			1.00	108.70	108.70
14	4	S53102-06510	GRILLE SUB-ASSY, RAD - BR (Burr)			1.00	599.80	599.80
15	5	S53128-06080	GRILLE, RADIATOR, LW - BR			1.00	30.50	30.50
16	6	S52422-06060	PAD, FR BUMPER, RH - BR			1.00	17.60	17.60
17	7	S52423-06060	PAD, FR BUMPER, LH - BR			1.00	17.60	17.60
18	8	S52535-06240	RETAINER, FR BUMPER - BR			1.00	93.70	93.70
19	9	S52536-06240	RETAINER, FR BUMPER - BR			1.00	93.70	93.70
20	0	S52611-06490	ABSORBER, FR BUMPER - BR			1.00	111.30	111.30
21	1	S52131-06210	REINFORCEMENT, FR BU - BT			1.00	387.00	387.00
22	2	S52618-06070	ABSORBER, FR BUMPER, - BR			1.00	200.50	200.50
23	3	T90467-05170	CLIP - BR			2.00	2.80	5.60
24	4	T47749-33030	CLIP, PIN HOLD - BR			4.00	9.50	38.00
25	5	T53879-33030	RETAINER, FR FENDER - BR			4.00	13.20	52.80
26	6	S53101-06C30	GRILLE SUB-ASSY, RAD - BR			1.00	418.20	418.20
27	7	S53123-06170	MOULDING, RADIATOR G - BR			1.00	66.20	66.20
28	8	S53124-06170	MOULDING, RADIATOR G - BR			1.00	66.20	66.20
29	9	S88210-06150	SENSOR ASSY, MILLIME - BR			1.00	2082.90	2082.90
30	0	S53301-06360	HOOD SUB-ASSY - BR			1.00	1766.00	1766.00
31	1	S53381-06230	SEAL, HOOD TO RADIAT - BR			1.00	57.50	57.50
32	2	S53341-06500	INSULATOR, HOOD - CRN			1.00	649.10	649.10
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang		
			Document No. 0		681B Jurong West Central 1 #14-72 Singapore 642681		
			Document Date 27/06/2022		Mobile: 92302911		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
33	3	T90467-09050 CLIP / <i>MC</i>	10.00	3.10		31.00	
34	4	S53802-06210 FENDER SUB-ASSY, FR <i>(LH)</i> / <i>00</i>	1.00	933.00		933.00	
35	5	S53510-06370 LOCK ASSY, HOOD <i>x nn</i>	1.00	146.80		146.80	
36	6	S53410-06460 HINGE ASSY, HOOD, RH <i>BT</i>	1.00	63.70		63.70	
37	7	S53420-06460 HINGE ASSY, HOOD, LH <i>BT</i>	1.00	63.70		63.70	
38	8	T90469-06005 CLAMP <i>x nn</i>	3.00	4.20		12.60	
39	9	S53630-06271 CABLE ASSY, HOOD LOC <i>x nn</i>	1.00	59.40		59.40	
40	0	S53481-06170 BRACKET, HOOD SUPPOR <i>x nn</i>	1.00	11.40		11.40	
41	1	S53205-06250 SUPPORT SUB-ASSY, RA <i>BT (centre)</i>	1.00	371.40		371.40	
42	2	S52081-06030 STAY SUB-ASSY, FR BU <i>BR</i>	2.00	41.60		83.20	
43	3	S53202-06260 SUPPORT SUB-ASSY, RA <i>x nn</i>	1.00	265.10		265.10	
44	4	S53203-06300 SUPPORT SUB-ASSY, RA <i>BT (LH)</i>	1.00	265.10		265.10	
45	5	S57104-06090 MEMBER SUB-ASSY, FR <i>x nn</i>	1.00	245.30		245.30	
46	6	S53253-06020 BRACKET, RADIATOR MO <i>x nn</i>	2.00	65.00		130.00	
47	7	S16594-F0030 GUIDE, RADIATOR AIR, <i>x nn</i>	1.00	48.70		48.70	
48	8	S16593-F0080 GUIDE, RADIATOR AIR, <i>CR4</i>	1.00	98.30		98.30	
49	9	S16595-F0080 GUIDE, RADIATOR AIR, <i>x nn</i>	1.00	90.40		90.40	
50	0	S16592-F0030 GUIDE, RADIATOR AIR, <i>x nn</i>	1.00	59.20		59.20	
51	1	S16691-F0070 PLATE, RADIATOR SIDE <i>x nn</i>	1.00	40.20		40.20	
52	2	S16695-F0070 PLATE, RADIATOR SIDE <i>x nn</i>	1.00	38.30		38.30	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

inchope

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details			
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911			
		Document No.					
		0					
		Document Date					
		27/06/2022					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B63HK504001631	A25A0331527	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
53	3	S53295-06230 SEAL, COOL AIR INTAK ? BR (Top of dash)	1.00	212.20		212.20
54	4	T90467-07217 CLIP ? X m	10.00	2.80		28.00
55	5	S57013-06030 BRACKET SUB-ASSY, FR ? X m	1.00	338.00		338.00
56	6	S57014-06040 BRACKET SUB-ASSY, FR ? X m	1.00	338.00		338.00
57	7	S55708-06330 LOUVER SUB-ASSY, COW ? X m	1.00	699.00		699.00
58	8	S53866-06170 SEAL, FR FENDER TO C ? X m	1.00	49.70		49.70
59	9	S53867-06170 SEAL, FR FENDER TO C ? X m	1.00	49.70		49.70
60	0	S81110-06E80 HEADLAMP ASSY, RH	1.00	4730.30		4730.30
61	1	S81150-06E80 HEADLAMP ASSY, LH	1.00	4730.30		4730.30
62	2	T81210-48051 LAMP ASSY, FOG X m	1.00	516.00		516.00
63	3	T81220-48051 LAMP ASSY, FOG, LH X m	1.00	516.00		516.00
64	4	T89348-33190 CLIP, ULTRASONIC	2.00	12.80		25.60
65	5	T89348-06110 RETAINER, ULTRASONIC	2.00	16.60		33.20
66	6	S86560-06110 HORN ASSY, SECURITY	1.00	145.90		145.90
67	7	S884A0-06070 CONDENSER ASSY, SUPP	1.00	2166.60		2166.60
68	8	S16400-F0030 RADIATOR ASSY ? BT	1.00	2556.20		2556.20
69	9	S16470-0V100 RESERVE TANK ASSY, R ? X m	1.00	205.90		205.90
70	0	S16360-F0030 FAN ASSY, W/MOTOR ? BR	1.00	4628.60		4628.60
71	1	T17750-25010 INLET ASSY, AIR ? BR	1.00	299.80		299.80
72	2	S17700-F0030 CLEANER ASSY, AIR WI ? X m	1.00	1307.00		1307.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	Less
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details		Account No.		Customer Details				
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681				
		Document No. 0						
		Document Date 27/06/2022		Mobile: 92302911				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G	
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On			
MR2B63HK504001631	A25A0331527	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
73	3	S08889-80102 COOLANT, SLIC&&& ? / MC			2.00	86.00		172.00
74	4	T53141-33130 GARNISH, RADIATOR ? / BR			1.00	1091.60		1091.60
Stew (LKK) 28/6/22 12:30 PM OD - M ML EXEPT - ? P/P M Bel by 10 dys								
For & on behalf of		LKK Auto Consultants hence notify the Repairer of the following:			Charge Summary		Total	45,265.00
Borneo Motors (Singapore) Pte Ltd		- To resurvey before after spray painting - To do a damaged part's Customer's Signature - Part prices are subject to confirmation						
		- Third party survey is not allowed - Noise or modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			Parts 35,412.60 Labour 9,412.40 Sublet 440.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00%	3,168.55
Acknowledged by Repairer							Less	0.00
Signature:							Amount Due	48,433.55
Date:								

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

Supplementary

ESTIMATE

Account Details		Account No.		Customer Details				
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang				
		Document No. 0		681B Jurong West Central 1 #14-72 Singapore 642681				
		Document Date 05/07/2022		Mobile: 92302911				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	16231	SKC7177G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	1	S52142-06180 ARM, FR BUMPER, UPR <i>/ BT</i>			1.00	49.70		49.70 <i>/</i>
2	2	S86510-06260 HORN ASSY, HIGH PITCH <i>/ BR</i>			1.00	140.10		140.10 <i>/</i>
3	3	S82114-06190 WIRE, ENGINE ROOM, N <i>/ Tn</i>			1.00	153.90		153.90 <i>/</i>
4	4	T90467-07217 CLIP <i>/ nk</i>			10.00	2.80		28.00 <i>/</i>
<i>Hom Assy, Low Pitch / BR \$140.10</i> <i>Steve CLKK</i> <i>5/7/22, 4:30pm</i>								
For & on behalf of		Customer's Signature		Charge Summary		Total		371.70
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		GST 7.00%		26.02
				Labour		Less		0.00
				Sublet				
				Lubrication/Fluid				
				Others				
						Amount Due		397.72

Company Copy