



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911		
			Document No. 0				
			Document Date 18/07/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	61681	15995	72/OD/SKC7177G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	29/06/2022	8.00	16/07/2022 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:SP2001891658 ACC DATE:27.06.2022 TOW IN:26.06.2022 EXCESS:\$600 DATE-IN:26.06.2022 DATE SURVEY:28.06.2022 NO OF REPAIR DAYS:10 WORKING DAYS BY:LKK-STEVE AUTHORISED ON:28.06.2022				50.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00	
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP	*			122.40	
4	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR	*			180.00	
5	B	BP-LAB2 TO RESET ECU AND REPROGRAMME	*			180.00	
6	B	BP-LAB2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SENSOR	*			180.00	
7	S	BP-SUBLET R/I AC CONDENSOR,PIPING AND REGAS	0742			360.00	
8	L	BP-LPO SUPPLY REGN PLATE (PO#)	0263			80.00	
9	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	*			2880.00	
10	B	BP-RES2 RESPRAY ACC AFFECTED AREAS	*			2950.00	
11	V	EXC Excess element of insurance repair to be paidby the insured party	8888			-600.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details					
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ	Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911					
		Document No. 0						
		Document Date 18/07/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	61681	15995	72/OD/SKC7177G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	29/06/2022	8.00	16/07/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	1	S52119-0X951	COVER, FR BUMPER, L			1.00	581.40	581.40
13	2	S52114-06460	BRACKET, FR BUMPER E			1.00	108.70	108.70
14	3	S53102-06510	GRILLE SUB-ASSY, RAD			1.00	599.80	599.80
15	4	S53128-06080	GRILLE, RADIATOR, LW			1.00	30.50	30.50
16	5	S52422-06060	PAD, FR BUMPER, RH			1.00	17.60	17.60
17	6	S52423-06060	PAD, FR BUMPER, LH			1.00	17.60	17.60
18	7	S52536-06240	RETAINER, FR BUMPER			1.00	93.70	93.70
19	8	S52611-06490	ABSORBER, FR BUMPER			1.00	111.30	111.30
20	9	S52131-06210	REINFORCEMENT, FR BU			1.00	387.00	387.00
21	0	S52618-06070	ABSORBER, FR BUMPER,			1.00	200.50	200.50
22	1	T90467-05170	CLIP			2.00	2.80	5.60
23	2	T47749-33030	CLIP, PIN HOLD			4.00	9.50	38.00
24	3	S53101-06C30	GRILLE SUB-ASSY, RAD			1.00	418.20	418.20
25	4	S53123-06170	MOULDING, RADIATOR G			1.00	66.20	66.20
26	5	S53124-06170	MOULDING, RADIATOR G			1.00	66.20	66.20
27	6	S53301-06360	HOOD SUB-ASSY			1.00	1766.00	1766.00
28	7	S53341-06500	INSULATOR, HOOD			1.00	649.10	649.10
29	8	T90467-09050	CLIP			10.00	3.10	31.00
30	9	S53802-06210	FENDER SUB-ASSY, FR			1.00	933.00	933.00
31	0	S53410-06460	HINGE ASSY, HOOD, RH			1.00	63.70	63.70
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961				S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911			
				Document No. 0					
				Document Date 18/07/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	61681	15995	72/OD/SKC7177G		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	29/06/2022	8.00	16/07/2022	18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
32	1	S53420-06460 HINGE ASSY, HOOD, LH			1.00	63.70		63.70	
33	2	S53205-06250 SUPPORT SUB-ASSY, RA			1.00	371.40		371.40	
34	3	S53203-06300 SUPPORT SUB-ASSY, RA			1.00	265.10		265.10	
35	4	S16593-F0080 GUIDE, RADIATOR AIR,			1.00	98.30		98.30	
36	5	S81110-06E80 HEADLAMP ASSY, RH			1.00	4730.30		4730.30	
37	6	S81150-06E80 HEADLAMP ASSY, LH			1.00	4730.30		4730.30	
38	7	T89348-33190 CLIP, ULTRASONIC			2.00	12.80		25.60	
39	8	S89348-06110 RETAINER, ULTRASONIC			2.00	16.60		33.20	
40	9	S884A0-06070 CONDENSER ASSY, SUPP			1.00	2166.60		2166.60	
41	0	S16400-F0030 RADIATOR ASSY			1.00	2556.20		2556.20	
42	1	S16360-F0030 FAN ASSY, W/MOTOR			1.00	4628.60		4628.60	
43	2	T17750-25010 INLET ASSY, AIR			1.00	299.80		299.80	
44	3	S08889-80102 COOLANT,SLLC&&&			2.00	86.00		172.00	
45	4	T53141-33130 GARNISH, RADIATOR			1.00	1091.60		1091.60	
46	5	S52142-06180 ARM, FR BUMPER, UPR			1.00	49.70		49.70	
47	6	S86510-06260 HORN ASSY, HIGH PITC			1.00	140.10		140.10	
48	7	S86520-06250 HORN ASSY, LOW PITCH			1.00	140.10		140.10	
49	8	S82114-06190 WIRE, ENGINE ROOM, N			1.00	153.90		153.90	
50	9	S52081-06030 STAY SUB-ASSY, FR BU			2.00	41.60		83.20	
51	0	S53295-06230 SEAL, COOL AIR INTAK			1.00	212.20		212.20	
For & on behalf of		Customer's Signature			Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle			Parts		Less		
					Labour				
					Sublet				
					Lubrication/Fluid				
					Others		Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911		
			Document No.				
			0				
			Document Date				
			18/07/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	61681	15995	72/OD/SKC7177G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B63HK504001631	A25A0331527	60	Thomas Pang W T	29/06/2022 8.00	16/07/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	1	T90467-07217 CLIP	10.00	2.80		28.00
53	2	S53395-06110 SEAL, HOOD TO FR END	1.00	71.90		71.90

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	34,879.30
	Please acknowledge receipt of vehicle	Parts 28,296.90	GST 7.00%	2,441.55
		Labour 6,742.40	Less	0.00
		Sublet 440.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	37,320.85

Customer Copy