



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	<b>Document No.</b>	: SQT22001828	<b>Page</b>	1
<b>Registration No</b>	: SNE5044Z	<b>Date</b>	: 28. Jun 2022	<b>Customer No.</b>	: WZL009
<b>Chassis No</b>	: JHMRV3800NS200133	<b>Svc Advisor</b>	: YOU PO SOON	<b>Engine No</b>	: L15ZK1100125
<b>Model</b>	: HRV DX-SIN CVT YM 2022	<b>Date   Time</b>	: 28. Jun 2022 8:03:07 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: TEOH LING LING	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 27/6/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04711-3N0-G00ZZ	FACE,FR.BUMPER <i>Torn</i>	1	535.70	25	401.77	28.12	429.89
71240-3M0-000	COR UP BEAM,R.FR <i>11</i>	1	49.80	X 25	37.35	2.61	39.96
71290-3M0-000	COR UP BEAM,L.FR <i>one</i>	1	49.80	25	37.35	2.61	39.96
71130-3M0-000ZZ	BEAM COMP,FR.BUMP <i>11</i>	1	358.80	X 25	269.10	18.84	287.94
71230-3M0-003	SPACER,R.FR.BPR S <i>11</i>	1	11.60	X 25	8.70	0.61	9.31
71280-3M0-003	SPACER,L.FR.BPR S <i>one</i>	1	11.60	25	8.70	0.61	9.31
71190-3M0-003	GARNISH ASSY,L.FR.FOG <i>garnish</i>	1	35.70	25	26.77	1.87	28.64
91505-TM8-003	CLIP,BUMPER <i>one</i>	20	2.30	25	34.50	2.42	36.92
71200-3M0-N01ZE	GRILLE ASSY,FR. <i>11</i>	1	839.30	X 25	629.47	44.06	673.53
60260-3M0-000ZZ	PANEL COMP,L.FR.F <i>R</i>	1	463.00	X 25	347.25	24.31	371.56
74157-3M0-J01	PROTECTOR,L.FR. W <i>Dis</i>	1	101.90	25	76.42	5.35	81.77
91501-TR0-003	CLIP,INNER FENDER <i>one</i>	12	2.80	25	25.20	1.76	26.96
33150-3M0-J41	HEADLIGHT ASSY,L. <i>one</i>	1	1782.40	25	1336.80	93.58	1430.38
42700-3M0-J71	DISK,ALUMINIUM WHEEL 18 <i>11</i>	1	725.20	X 25	543.90	38.07	581.97
	<b>Sum Item</b>				<b>3783.28</b>	<b>264.82</b>	<b>4,048.10</b>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4 <i>11</i>	1	180.00	X	180.00	12.60	192.60
	<b>Sum Ext. Service</b>				<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
BOSUN	SUNDRIES <i>11</i>	1	50.00	20	50.00	3.50	53.50

Printed on 28/6/2022 8:14:08 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD  
300 BEACH ROAD #17-04/07  
THE CONCOURSE  
SINGAPORE 199555

Registration No : SNE5044Z

Chassis No : JHMRV3800NS200133

Model : HRV DX-SIN CVT YM 2022

Owner's Name : TEOH LING LING

Ins Policy No. :

Date of Accident : 27/6/2022

Document No. : SQT22001828  
Date : 28. Jun 2022  
Customer No. : WZL009  
Svc Advisor : YOU PO SOON  
Engine No : L15ZK1100125  
Date | Time : 28. Jun 2022 8:03:07 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	120	180.00	12.60	192.60	
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00	11X	480.00	33.60	513.60	
BKFE11R	REMOVE & RENEW FR L FENDER INCLUDING 650	1	2100.00	1300	2100.00	147.00	2247.00	
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P) 570	1	2200.00	1500	2200.00	154.00	2354.00	
					<b>Sum Labor</b>	<b>5010.00</b>	<b>350.70</b>	<b>5,360.70</b>

Survey By Marcus Lee

Date & Time 05/07/22 @ 10.15am

Excess \_\_\_\_\_

Status Not Approved

Signature Take photo before painting

4 days.

**Total Amount** 8,973.28 628.12 9,601.40

**Total (Inclusive of GST)** 9,601.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Printed on 28/6/2022 8:14:08 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.