

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS4/FWD22006148/NCY3E2

Date: 25/07/2022

REFERENCE

Insured/Claimant:	LIM SAI SOON	Policy No:	PNPV2020-00000904-01	
Date of Loss:	26/06/2022	Nature of Claim:	OD	Claim No: 1202200013423

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW4323Z		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4026790
Reg. Date:	14/01/2016 (Man. Year: 2015)	Chassis No:	RU11106786
Colour:	Black	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	750.00	-750.00	
Nett Amount (S\$)	0.00	-750.00	750.00	

INSPECTION

Date of Assignment:	28/06/2022	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	30/06/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	0.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$54,000.00
OMV :	\$18,800.00
PARF Rebate (1) :	\$ 5,720.00
Quota Premium Paid :	\$56,001.00
COE Rebate (2) :	\$19,826.00
Total Rebate (1) + (2) = :	\$25,546.00

The total amount incurred will be Market Value \$54,000.00 minus Total Rebate \$25,546.00 = \$28,454.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDW4323Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >